

منابع

- ASM Handbook Vol.16
- Machining technology : machine tools and operations
 - Helmi A. Youssef, Hassan El-Hofy
- Metal Machining: Theory and Applications
 - Thomas Childs

• ابزار شناسی و ماشینکاری
• دکتر رازفر

• Lecture 1: Machining Technology

Dr. Parviz Kahhal •2

بنام خدا: ابزار شناسی و ماشینکاری

Dr. Parviz Kahhal

سرفصل مطالب

- Chapter 1 Machining Technology
- Chapter 2 Basic Elements and Mechanisms of Machine Tools
- Chapter 3 General-Purpose Machine Tools
- Chapter 4 Thread Cutting
- Chapter 5 Gear Cutting Machines and Operations
- Chapter 6 Turret and Capstan Lathes
- Chapter 7 Automated Lathes
- Chapter 8 Numerical Control and Computer Numerical Control Technology

• Lecture 1: Machining Technology

Dr. Parviz Kahhal •4

نحوه امتیاز دهی

- پایاتترم ۱۵ نمره
- پروژه ۵ نمره

• Lecture 1: Machining Technology

Dr. Parviz Kahhal •3

سر فصل مطالب

- Chapter 9 Hexapods and Machining Technology
- Chapter 10 Machine Tool Dynamometers
- Chapter 11 Nontraditional Machine Tools and Operations
- Chapter 12 Environment-Friendly Machine Tools and Operations
- Chapter 13 Design for Machining
- Chapter 14 Accuracy and Surface Integrity Realized by Machining Processes
- Chapter 15 Automated Manufacturing System

مقدمه

- ساخت یک فعالیت صنعتی است که شکل مواد خام را در جهت تولید محصولات تغییر می دهد.
- ریشه اصلی واژه manufacture به معنی ساخته شده توسط دست می باشد.
- با توجه به اینکه توان ابزار های دستی پایین می باشد، امروزه ساخت به صورت گسترده ای توسط ماشین آلات انجام می شود.
- تکنولوژی ساخت تمامی روش های مورد استفاده برای شکل دادن مواد خام به محصولات نهایی را در بر می گیرد.

Lecture 1: Machining Technology

Dr. Parviz Kahhal




FIGURE 1.2 Definition of manufacturing.





FIGURE 1.1 Classification of manufacturing processes.



مقدمه

- ماشینکاری برداشت ماده ناخواسته از قطعه کار برای دستیابی به قطعه نهایی با اندازه، شکل و صافی سطح مطلوب می باشد.
- عمل برداشت ماده با استفاده از روش های برش در ابتدا با ابزار های دستی ساخته شده از استخوان، چوب، یا سنگ انجام می شه است که این ابزار ها بعدا جای خود را به ابزار های برنزی و فولادی دادند.
- آب، بخار و بعدا الکتریسیته برای راندن و هدایت این ابزار ها در ماشین های ابزار به کار گرفته شده اند.
- توسعه مواد ابزار جدید یک دریچه جدید را به روی صنعت ماشینکاری باز نموده است.
- تکنیک های ماشینکاری غیر سنتی روش های جایگزینی برای ماشینکاری قطعات با ماده سخت تر، محکمتر، و چقرمه تر شده اند که ماشینکاری آن ها با روش های سنتی مشکل می باشد.

تاریخچه ماشین ابزار

- The development of metal cutting machines (once briefly called machine tools) started from the invention of the cylinder, which was changed to a roller guided by a journal bearing.
- The ancient Egyptians used these rollers for transporting the required stones from a quarry to the building site.
- The use of rollers initiated the introduction of the first wooden drilling machine, which dates back to 4000 bc.
- In such a machine, a pointed flint stone tip acted as a tool. The first deep hole drilling machine was built by Leonardo da Vinci (1452–1519).
- In 1840, the first engine lathe was introduced.

مقدمه

- در مقایسه به تکنولوژی شکل دهی پلاستیک، تکنولوژی ماشینکاری معمولا در مواردی به کار گرفته می شود که دقت قطعه و کیفیت سطح اهمیت بیشتری دارند.
- ماشینهای ابزار حدود ۷۰٪ عملیات ماشینهای تولیدی را انجام می دهند.
- عملیات های ماشینکاری تقریبا ۲۰٪ فعالیت های ساخت را در ایالات متحده در برمی گیرند.

HISTORY OF MACHINE TOOLS

- In 1818, Whitney built the first milling machine; the cylindrical grinding machine was built for the first time by Brown and Sharpe in 1874.
- The first gear shaper was introduced by Fellows in 1896.
- In 1879, Pfauter invented the gear hobber, and the gear planers of Sunderland were developed in 1908.

HISTORY OF MACHINE TOOLS

- Maudslay (1771–1831) added the lead screw, back gears, and the tool post to the previous design. Later, slide ways for the tailstock and automatic tool feeding systems were incorporated.
- Planers and shapers have evolved and were modified by Sellers (1824–1905). Fitch designed the first turret lathe in 1845. That machine carried eight cutting tools on a horizontally mounted turret for producing screws.
- A completely automatic turret lathe was invented by Spencer in 1896. He was also credited with the development of the multispindle automatic lathe.




FIGURE 1.5 Wooden planer machine (1855).




FIGURE 1.4 First wooden lathe machine.

TABLE 1.1

Developments of Machine Tools

1200–1299	Horizontal bench lathe appears, using foot treadle to rotate object
1770	Screw-cutting lathe invented: first to get satisfactory results (Ramsden, Britain)
1810	Lead screw adapted to lathe, leading to large-quantity machine-tool construction (Maudslay, Britain)
1817	Metal planing machine (Roberts, Britain)
1818	Milling machine invented (Whitney, United States)
1820–1849	Lathes, drilling, boring machines, and planers (most primary machine tools) refined
1830	Gear-cutting machine with involute cutters and geared indexing improved (Whitworth, Britain)
1830–1859	Milling machines, shapers, and grinding machines (United States)
1831	Surface-grinding machine patented (J. W. Stone, United States)
1834	Grinding machine developed: perhaps first (Wheaton, United States)
1836	Shaping machine invented; Whitworth soon added crank mechanism (Nasmyth, Britain)
1840 ca.	Vertical pillar drill with power drive and feed in use (originated in 1750)
1842	Gear-generating machine for cutting cycloidal teeth developed (Saxton, United States)
1850	Commercially successful universal milling machine designed (Robbins and Lawrence, Howe, and Windsor, United States)
1853	Surface grinder patented (Darling, United States)
1854 ca.	Commercial vertical turret lathe built for Robbins and Lawrence by Howe and Stone (Stone, Howe, Lawrence, United States)
1857	Whitney gauge lathe built (Whitney, United States)
1860–1869	First cylindrical grinder made; replaces single-point tool of engine lathe (United States)
1860–1879	Universal milling (1861–1865) and universal grinding machines (1876) produced (Brown and Sharpe, United States)

● Lecture 1: Machining Technology

Dr. Parviz Kahhal ● 14



FIGURE 1.6 First industrial EDM machine in the world. Presentation of the Eleroda DI at the EMO exhibition in Milan Italy, 1955. (Courtesy of Charmilles, 560 Bond St., Lincolnshire, IL.)

حرکت های اصلی در ماشین ابزار

- در ماشین ابزار سنتی، تعداد زیادی از مشخصه های محصول با کمک حرکت ابزار یا قطعه کار تولید می شوند.
- شکل ابزار نقش قابل توجهی در سطح نهایی به دست آمده دارد.
- اساساً دو حرکت اصلی در یک ماشین ابزار وجود دارد:
 - حرکت اولیه، کلاً به ابزار یا قطعه کار داده می شود و سرعت برش را معین می کند.
 - حرکت ثانویه که ابزار را نسبت به قطعه کار تغذیه می کند.
- در برخی موارد حرکت اولیه به صورت ترکیبی به ابزار و قطعه کار داده می شود.

● Lecture 1: Machining Technology

Dr. Parviz Kahhal ● 16

1873	Automatic screw machine invented (1893, produced finished screws from coiled wire—A2) (Spencer, United States)
1887	Spur-gear hobbing machine patented (Grant, United States)
1895	Multispindle automatic lathe introduced for small pieces (United States)
1896–1940	Heavy-duty precision, high production rate grinding machine introduced at Brown and Sharpe (Norton, United States)
1921	First industrial jig borer made for precision machining: based on 1912 single-point tool (Société Genevoise, Switzerland)
1943	Electrodischarge machining (spark erosion) developed for machine tool manufacturing
1944–1947	Centerless thread-grinding machine patented (Scrivener, Britain; United States)
1945	The USM was patented by Balamuth
1947	The first prototype of EBM was designed by Steigerwald
1950	Electrochemical machines introduced into industry
1952	Alfred Herbert Ltd.'s first NC machine tool operating
1958	Laser phenomenon first predicted by Schawlow and Townes

Source: ASME International, 3 Park Ave., New York. With permission.

● Lecture 1: Machining Technology

Dr. Parviz Kahhal ● 15

Tool and WP Motions for Nontraditional Machine Tools

Machining Process	WP		Tool		Remarks
	Stationary ●	Feed Movement ↓	Stationary ●	Feed Movement ↓	
Chemical (erosion)					In the slitting processes (plate cutting), a relative motion between tool and WP (transverse speed v_t) is imparted in horizontal directions (X, Y).
CHM	●		●		
ECM (sinking)	●	↓			
Thermal (erosion)					
EDM (sinking)	●	↓			
EBM (drilling)	●		●		
LBM (drilling)	●		●		
PBM (drilling)	●		●		
Mechanical (abrasion)					
USM	●	↓			
AJM	●		●		
WJM	●		●		
Abrasive water jet machining (AWJM)	●		●		

Note: ↻, Rotation; ●, stationary; →, linear motion; - - - →, intermittent.


● Lecture 1: Machining Technology Dr. Parviz Kahhal ● 18

Tool and WP Motions for Machine Tools Used for Traditional Machining

Machining Process	Tool and WP Movements		Remarks
	v	f	
Chip removal			
Turning	WP ↻	Tool →	WP stationary
Drilling	Tool ↻	Tool →	
Milling	Tool ↻	WP →	
Shaping	Tool ↻	WP →	Intermittent feed
Planing	WP ↻	Tool →	
Slotting	Tool ↻	WP →	
Broaching	Tool ↻	WP →	Feed motion is built in the tool
Gear hobbing	WP ↻	Tool →	
	Tool ↻	Tool →	
Abrasion			
Surface grinding	Tool ↻	WP →	
Cylindrical grinding	Tool ↻	WP →	
	Tool ↻	Tool or WP →	
Honing	Tool ↻	WP →	WP stationary
Superfinishing	WP ↻	Tool →	

Note: ↻, Rotation; ●, stationary; →, linear motion; - - - →, intermittent.


● Lecture 1: Machining Technology Dr. Parviz Kahhal ● 17



مفاهیم تکنولوژی ماشینکاری

- تکنولوژی ماشینکاری رنج وسیعی از مفاهیم را در بر می گیرد که درک آن ها برای انتخاب های مهم در فرآیند الزامی می باشد.
- ابزار شناسی، ضمام و ماشین ابزار، طبیعت عملیات ماشینکاری روی یک ماده خاص را تعیین می کنند.
- هدف اصلی تکنولوژی ماشینکاری تولید اقتصادی و با نرخ بالای قطعه می باشد.
- قطعات در سطوح مختلف دقت، بافت سطح، و یکپارچگی سطح ماشینکاری می شوند تا به حالت مطلوب طراح رسیده و از عملیات های بعد از ماشینکاری در جهت کاهش هزینه جلوگیری شود.

● Lecture 1: Machining Technology Dr. Parviz Kahhal ● 19



مفاهیم تکنولوژی ماشینکاری: ماشین ابزار

- هر ماشین ابزار قابلیت انجام چند عملیات ماشینکاری را برای تولید قطعه مورد نیاز با دقت و صافی سطح مشخص شده را دارد.
- ماشینکاری روی ماشین ابزارهای متنوعی با اهداف عمومی انجام می شود که به ترتیب عملیات هایی شامل تکنیک های براده برداری و سایش را انجام می دهند و سطوح استوانه ای و تخت را تولید می کنند.
- به علاوه، ماشین ابزار های با اهداف خاص نیز برای تولید چرخنده، پیچ، و شکل های خاص دیگر استفاده می شوند.
- تکنولوژی پرداخت کاری برای هندسه های مختلف شامل سنگ زنی، هونینگ، لپینگ و تکنیک های پرداخت پیشرفته می باشد.

مفاهیم تکنولوژی ماشینکاری: ماشین ابزار

- ماشین های ابزار نیمه اتوماتیک حرکات کنترل شده اتوماتیک را انجام می دهند، در حالیکه قطعه کار به صورت دستی باز و بسته می شود.
- در ماشین های ابزار تمام اتوماتیک جابجایی قطعه کار و برش و همچنین عملیات های کمکی دیگر به صورت اتوماتیک انجام می شوند.
- ماشین های ابزار نیمه و تمام اتوماتیک بهترین انتخاب برای تولید محصولات با تعداد زیاد می باشند
- نقش اپراتور کمینه یا کاملاً حذف شده و قطعات دقیق تر و اقتصادی تر تولید می شوند.

مفاهیم تکنولوژی ماشینکاری: ماشین ابزار

- نمونه های ماشین ابزار با اهداف عمومی
- تراشکاری
- سوراخکاری
- فرز
- سنگ زنی
- خان کشی
- Jig boring
- لپینگ
- ماشینهای با اهداف خاص
- چرخنده زنی
- رزوه زنی
- دقت محصول در حین ماشینکاری بستگی به مشارکت اپراتور در عملیات دارد.
- ماشین های Capstan و turret ماشین های رایجی هستند که نقش اپراتور را در ماشینکاری قطعه کاری ها میله ای و برقو شکل در نرخ ها و دقت های بالا، کاهش می دهد.

مفاهیم تکنولوژی ماشینکاری: ماشین ابزار


- هگزایاد ها زمینه جدیدی از ماشینکاری را خلق نموده اند که می توان قطعات پیچیده را با یک ابزار که قابلیت دارد از هر طرف به قطعه کار برسد، ماشینکاری نمود.
- هگزایاد شش درجه آزادی در حرکت دارد و قابلیت یک ربات و صلیبیت و دقت یک ماشین ابزار را دارد.
- برای ماشینکاری با اهداف عمومی، هگزایاد یک ماشین ابزار ایده آل برای ماشینکاری قالب می باشد.

مفاهیم تکنولوژی ماشینکاری: ماشین ابزار

- ماشین های ابزار NC فرمی از اتوماسیون توسط اعداد، حروف و سمبل ها می باشند که از یک واحد کنترل و نوارخوان استفاده می کنند، در حالیکه ماشین های ابزار CNC از یک برنامه کامپیوتری ذخیره شده برای انجام تمام عملکرد های NC بهره می گیرند.
- NC و CNC مزایای زیادی را به تکنولوژی ماشینکاری اضافه کرده اند،
 - تعداد کم و زیاد قطعات قابل تولید هستند،
 - هندسه قطعات از طریق کنترل انعطاف پذیر برنامه قطعات، قابل تغییر می باشد.
- یکپارچه سازی سیستم های CAD/CAM با تکنولوژی ماشینکاری، زمینه های صنعتی جدیدی را خلق نموده است.

مفاهیم تکنولوژی ماشینکاری: ماده قطعه کار

- ماده قطعه کار در انتخاب روش ماشینکاری اثرگذار می باشد.
- اغلب مواد را می توان با طیفی از فرآیند ها ماشینکاری نمود، و برخی را فقط با یک طیف محدود می توان ماشینکاری نمود.
- در هر حالت خاص، انتخاب ماده به شکل و اندازه، تolerانس ابعادی، صافی سطح و مقدار مطلوب بستگی دارد.
- همچنین این انتخاب تنها به تناسب تکنیکی بستگی ندارد، بلکه به ملاحظات اقتصادی و زیست محیطی نیز بستگی دارد.



مفاهیم تکنولوژی ماشینکاری: دقت و یکپارچگی سطح

- انتخاب یک تکنولوژی ماشینکاری به دقت و صافی سطح مورد نظر بستگی دارد.
- زیر سطح ماشینکاری برخی تغییرات در نتیجه مکانیزم براده برداری انتخاب شده به وجود می آیند.
- آزمایش دقیق این لایه بسیار مهم است.
- این لایه در خصوصیات قطعات ماشینکاری شده از قبیل استحکام خستگی، خوردگی و مقاومت به سایش تاثیر گذار می باشد.
- در برخی موارد، ممکن است یک تکنولوژی فرا پرداخت (Post Finishing) برای حل برخی مشکلات به کار گرفته شود که این هزینه تولید را بالا می برد.

مفاهیم تکنولوژی ماشینکاری: بهره وری ماشینکاری

- در انتخاب هر روش ماشینکاری باید نرخ تولید که با زمان ماشینکاری نسبت معکوس دارد، در نظر گرفته شود.
- روش های افزایش بهره وری شامل موارد زیر می باشند:
- سرعت های بالای ماشینکاری
- نرخ های تغذیه بالا
- کمینه سازی زمان غیر ماشینکاری
- مکانیزم های اتوماتیک تعویض ابزار و تغذیه
- چگالی های بالای توان

مفاهیم تکنولوژی ماشینکاری: اثرات محیطی ماشینکاری

- خطرات محتمل تکنولوژی انتخاب شده ممکن است بر سلامت اپراتور، ماشین ابزار و محیط پیرامون اثر داشته باشد.
- کاهش این خطرات نیازمند مانیتورینگ دقیق، آنالیز، درک و کنترل در جهت تکنولوژی ماشینکاری از نظر زیست محیطی پاک می باشد.
- خطرات تولید شده توسط مایعات برشی باعث معرفی روش های روانکاری با مقدار کمینه (MQL) ، ماشینکاری Cryogenic و تکنیک های ماشینکاری خشک شده است.

مفاهیم تکنولوژی ماشینکاری: طراحی قطعه برای ماشینکاری اقتصادی

- این مفهوم در تولید قطعات دقیق و اقتصادی بسیار مهم می باشد.
- توصیه های طراحی قطعات برای هر عملیات باید دقیقاً توسط طراح قطعه رعایت شوند.
- باید از پیچیدگی های طراحی اجتناب شود تا زمان ماشینکاری کاهش و به تبع آن نرخ تولید افزایش یابد.
- قابلیت ماشین ابزار و عملیات بر اساس دقت و صافی سطح ممکن نیز باید در نظر گرفته شود، تا بهترین روش، ماشین ابزار و عملیات انتخاب شود.

Lecture 2: Basic Elements and Mechanisms of Machine Tools

Dr. Parviz Kahhal

مقدمه

- مشخصه ماشین های برش فلزات (ماشین ابزار) نسبت به ماشین های شکل دهی فلزات، دقت تولید بالاتر می باشد.
- آن ها برای تولید تعداد نسبتاً کمتری استفاده می شوند، بالعکس، ماشین های شکل دهی فلزات برای کمیت های تولید بالاتر استفاده می شوند.
- ماشین های ابزار حدود ۷۰٪ از ماشین های عملیاتی تولیدی را در صنعت تشکیل می دهند.
- درصد های مختلف عملیات های مختلف ماشین های ابزار در اسلاید بعدی نشان داده شده اند.

مقدمه

TABLE 2.1

Percentage of Different Types of Operating Machine Tools

Type of Machine Tool	Percentage
Lathes including automatics	34
Grinding	30
Milling	15
Drilling and boring	10
Planers and shapers	4
Others	7

مقدمه

- طراحی موفق ماشین ابزار نیازمند معلومات بنیادی زیر می باشد:
 1. مکانیک فرآیند های ماشینکاری برای ارزیابی مقدار و جهت و همچنین کنترل نیرو های برش.
 2. قابلیت ماشینکاری مواد مختلف که قرار است ماشینکاری شوند
 3. خواص مواد مورد استفاده برای ساخت قطعات مختلف یک ماشین ابزار
 4. تکنیک های ساخت که برای تولید هرکدام از قطعات ماشین ابزار به صورت اقتصادی به کار گرفته می شوند.
 5. ماندگاری و قابلیت مواد ابزار مختلف
 6. اصول اقتصاد مهندسی

مقدمه

- قابلیت تولید یک ماشین ابزار توسط
 - تعداد قطعه تولید شده در واحد زمانی،
 - یا نرخ براده برداری حجمی،
 - یا نرخ براده برداری مخصوص به ازای توان واحد مصرف شده،
- اندازه گیری می شود.
- سطح قابلیت تولید (بهره وری) را می توان با استفاده از روش های زیر ارتقا بخشید:
 1. افزایش سرعت ها و نرخ تغذیه ماشین
 2. افزایش توان در دسترس ماشین ابزار
 3. استفاده از چند ابزار و یا ماشینکاری چند قطعه کار به صورت همزمان
 4. افزایش سرعت حرکت واحد های اجرایی در زمان های غیر ماشینکاری
 5. افزایش سطح اتواسیون برای واحد های اجرایی ماشین های ابزار و اجزا قابل تعویض
 6. به کارگیری تکنیک های کنترل مدرن نظیر NC و CNC
 7. انتخاب مناسب فرآیند های ماشینکاری بر اساس ماده، پیچیدگی شکل، دقت و صافی سطح قطعه ماشینکاری شده.
 8. به کارگیری قید ها و بند ها که قطعه کار را در کمترین زمان ممکن مکان یابی و محکم می کند.

مقدمه

- ماشین های ابزار به گونه ای طراحی شده اند که ماکزیمم بهره وری ممکن را به دست آورند و دقت و صافی سطح پیش بینی شده را در عمر سرویس دهی خود مهیا نمایند.
- برای ارضا این نیاز ها، هر جزء ماشین ابزار باید به صورت جداگانه و تا حد امکان صلب طراحی شود و سپس از نظر رزونانس و استحکام بررسی شود.
- به علاوه، ماشین ابزار باید یک پایداری مناسب داشته و دارای ویژگی های کلی زیر باشد:
 1. سفتی استاتیکی بالا برای همه اجزا ماشین ابزار مانند ساختار، مفاصل، و اسپیندل ها.
 2. جلوگیری از فرکانس های طبیعی غیر قابل قبول که باعث رزونانس در ماشین ابزار می شوند.
 3. سطح ارتعاش قابل قبول
 4. ظرفیت میرایی مناسب
 5. سرعت و نرخ تغذیه بالا
 6. نرخ های سایش پایین در قطعات لغزشی
 7. اعوجاج حرارتی پایین برای اجزا مختلف ماشین ابزار
 8. هزینه پایین طراحی، توسعه، تعمیر، نگهداری و ساخت.

مقدمه

- ماشین های ابزار بر طبق ویژگی هایشان به انواع زیر دسته بندی می شوند:
 1. ماشین های با اهداف عمومی (انیورسال)، که برای ماشینکاری طیف وسیعی از محصولات به کار می روند.
 2. ماشین های با اهداف خاص، که برای ماشینکاری محصولات با شکل یکسان و اندازه متفاوت به کار می روند.
 3. ماشین های با اهداف محدود، که یک طیف باریک از عملیات ها را روی محصولات گوناگون انجام می دهند.

مقدمه

- ماشین های ابزار بر اساس سطح دقت به انواع زیر دسته بندی می شوند:
 1. ماشین های ابزار با دقت معمولی، که شامل اکثر ماشین های با اهداف عمومی می باشد.
 2. ماشین های ابزار با دقت بالاتر، قابلیت تولید تolerانس های پایبتر را دارند.
 3. ماشین های ابزار با دقت بسیار بالا، که قابلیت تولید قطعات بسیار دقیق را دارند.

مقدمه

- عملکردهای اصلی یک ماشین ابزار نگه داری قطعه کار، نگه داری ابزار و دستیابی به حرکات نسبی مورد نیاز برای تولید هندسه مطلوب قطعه می باشد.
- ماشین های ابزار شامل اجزا زیر می باشند:
 1. یک ساختار متشکل از بستر (میز)، ستون، یا قاب
 2. لغزنده ها و ضمامم ابزار
 3. اسپیندل ها و یاتاقان های اسپیندل ها
 4. یک سیستم راننده (واحد توان یا تغذیه)
 5. اجزا نگه دارنده ابزار و قطعه کار
 6. سیستم های کنترل
 7. یک اهرم بندی انتقال


مقدمه

- تنش های تولید شده در حین ماشینکاری، که تمایل به تغییر شکل ماشین ابزار و یا قطعه کار دارند، معمولا توسط یکی از فاکتور های زیر به وجود می آیند:
 1. بار های استاتیکی شامل وزن ماشین و قطعات مختلف
 2. بارهای دینامیکی که توسط قطعات دورانی یا رفت و برگشتی به وجود می آیند.
 3. نیروهای برشی تولید شده توسط فرآیند براده برداری
- بار های استاتیکی و دینامیکی روی کارآیی ماشین در مرحله پرداخت تاثیر می گذارند.
- درجه نهایی دقت نیز تحت تاثیر تغییر مکان ناشی از نیروهای برشی قرار می گیرد.


ساختار ماشین های ابزار

- ساختار ماشین ابزار شامل یک بدنه، که بقیه قطعات ماشین را تحمل و در خود جا می دهد، می باشد.
- شکل اسلاید بعد یک بستر ماشین ابزار رایج مربوط به ماشین تراش و یک قاب ماشین دریل را نشان می دهد.
- عملکرد های اصلی ساختار ماشین شامل موارد زیر می باشند:
 1. قابلیت ساختار یا بستر برای مقومت در برابر اعوجاج ناشی از بار های استاتیکی و دینامیکی
 2. پایداری و دقت قطعات متحرک
 3. مقاومت به سایش شیار هدایت کننده (راهنما)
 4. عاری از تنش های پسماند
 5. میرا کننده ارتعاش

ساختار ماشین های ابزار



Lathe bed




Frame of radial drill

FIGURE 2.1 Typical bed of center lathe and frame of a drilling machine.


ساختار ماشین های ابزار

- ساختار ماشین های ابزار به دو دسته قاب های باز و بسته تقسیم می شوند.
- قاب های باز قابلیت دسترسی عالی به ابزار و قطعه کار را فراهم می کند. نمونه های رایج قاب های باز را می توان در ماشین های تراش، فرز، سنگ زنی، شیار زنی و داخل تراشی مشاهده نمود.
- قاب های بسته را می توان در ماشین های صفحه تراش و فرز های با دو اسپیندل مشاهده نمود.
- ساختار یک ماشین ابزار ابزار و قطعه کار را گرفته و راهنمایی می کند و موقعیت نسبی آن ها را در حین فرآیند ماشینکاری فراهم می کند.
- ساختار های ماشین ابزار باید به گنواهی طراحی شوند که بدون تغییر مکان، نیرو های برش و وزن قطعات متحرک را به شاسی منتقل نمایند.

ساختار ماشین های ابزار




Slotting machine



Boring machine

Examples of open frames (C-frames).

ساختار ماشین های ابزار



ساختار ماشین های ابزار

- پیکر بندی ساختار ماشین ابزار توسط چیدمان حرکات ضروری برش و تغذیه و طول کورس آن ها و اندازه و ظرفیت ماشین مقرر می شود.
- در همین راستا، انهدام براده، حمل و نقل، نصب و نگهداری نیز در نظر گرفته می شوند.
- نرخ برداشت ماده تعیین کننده ظرفیت توان ماشین ابزار و در نتیجه مقدار نیروهای برشی خواهد بود.
- درجه دقت تولید تحت تاثیر تغییر شکل و خیز ساختار است، که باید در حدود تعریف شده نگاه داشته شوند.
- ارزشیابی رفتار ماشین ابزار توسط ارزیابی خصوصیات استاتیکی و دینامیکی آن انجام میگیرد.


ساختار ماشین های ابزار

- **خصوصیات استاتیکی**
- این خصوصیات در رابطه با خیز (تغییر مکان) ثابت تحت عوامل زیر می باشند.
 1. بارهای عملیاتی برشی ثابت
 2. وزن اجزا متحرک
 3. اصطکاک
 4. نیروهای اینرسی
- این عوامل بر روی دقت قطعات ماشینکاری شده موثرند و معمولا توسط سفتی استاتیکی اندازه گیری می شوند.
- **خصوصیات دینامیکی**
- این خصوصیات اغلب توسط خیز دینامیکی و فرکانس های طبیعی تعیین می شوند.
- این خصوصیات بر پدیده چتر ماشین ابزار و در نتیجه پایداری عملیات ماشینکاری موثرند.

ساختار ماشین های ابزار

- خیز استاتیکی و دینامیکی یک ماشین ابزار به موارد زیر بستگی دارد:
 1. کدامیک از نیروهای عملیاتی منتقل و توزیع می شوند
 2. رفتار هر واحد ساختاری تحت شرایط عملیاتی
- جز تیر مانند، با سطح مقطع مستطیل توخالی، برجسته ترین جز می باشد.
- ساختار های با قاب بسته، با اینکه تحت تاثیر بار، تغییر شکل می دهند، امتداد محور های مرکزی ان ها بدون تغییر باقی می ماند.
- بر همین اساس ، در یک جابجایی محوری (نه جانبی) ابزار نسبت به قطعه کار دقت تغییر نمی کند.
- قاب های باز را می توان با یک جز دیگر ساپورت نمود.

ساختار ماشین های ابزار




Hollow box sections of the lathe bed.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal © 19

ساختار ماشین های ابزار




Deformation in open and closed frames.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal © 20

ساختار ماشین های ابزار



Radial drilling machine with end support.

● Lecture 2: Basic Elements and Mechanisms



Dr. Parviz Kahhal ● 21

ساختار ماشین های ابزار

- سفتی و میرایی ساختار ماشینیت ابزار به تعداد و نوع مفاصل مورد استفاده برای اتصال اجزا مختلف ساختار بستگی دارد.
- هر چه تعداد مفاصل کمتر باشد، سفتی ساختار بیشتر و قابلیت میرایی آن کمتر می باشد.
- سیستم دنده ای (Ribbing System) یک روش موثر برای افزایش سفتی ساختار ماشین ابزار می باشد.
- در شکل اسلاید بعد، پشت بند های عمودی، سفتی را در برابر خمش عمودی افزایش می دهند ولی در خمش افقی تاثیری ندارند.
- چیدمان پشت بند های قطری، سفتی ساختار را در برابر خمش و پیچش افزایش می دهد.
- در برخی موارد، برای از بین بردن حرکت نوسانی که معمولاً روی دسته انتهایی عمل می کند، از راهنما های عقبی بلند تر استفاده می شود (اسلاید ۲۸)
- قاب های ماشین های ابزار می توانند ریخته گری شده یا جوشکاری شوند. ساختار های جوشکاری شده از لحاظ هزینه به صرفه تر می باشند.

● Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal ● 22




ساختار ماشین های ابزار


- Figure 2.9 shows typical cast and fabricated machine tool structures.
- A cast iron (CI) structure ensures the following advantages:
 - Better lubricating property (due to the presence of free graphite);
 - most suitable for beds in which rubbing is the main criterion
 - High compressive strength
 - Better damping capacity
 - Easily cast and machined

MACHINE TOOL STRUCTURES

(a)



(b)



Cast and fabricated structures: (a) cast and (b) welded machine tool bases.

MACHINE TOOL STRUCTURE: LIGHT- AND HEAVY-WEIGHT CONSTRUCTIONS

- Machine tool structures are classified according to their natural frequency as light- or heavy-weight construction.
- The natural frequency ω_0 of a machine tool can be described by:

$$\omega_0 = \sqrt{\frac{k}{m}}$$

k = structure static stiffness

m = mass

$$k = \frac{F}{\delta}$$

F = force (N)

δ = deflection (mm)

MACHINE TOOL STRUCTURE: LIGHT- AND HEAVY-WEIGHT CONSTRUCTIONS

- To avoid resonance and thus reduce the dynamic deflection of the machine tool structure, ω_0 should be far below or far above the exciting frequencies, which is equal to a multiple of the rotational speed of the machine.
- If the natural frequency of the machine structure is kept far below the speed working range of the machine tool then

$$\omega_0 < \text{exciting frequency}$$

$$\sqrt{\frac{k}{m}} < \text{exciting frequency}$$

MACHINE TOOL STRUCTURE: LIGHT- AND HEAVY-WEIGHT CONSTRUCTIONS


- This requirement is achieved by the increase of the mass m , which, in turn, leads to a heavyweight construction. On the other hand, lightweight constructions are made when

$$\omega_0 > \text{exciting frequency}$$

$$\sqrt{\frac{k}{m}} > \text{exciting frequency}$$

MACHINE TOOL STRUCTURE: LIGHT- AND HEAVY-WEIGHT CONSTRUCTIONS


- Chip disposal, in the case of high-production machine tools, affects the construction of the machine tool frame as shown in Figure 2.10.



Chip disposal in a lathe bed.

MACHINE TOOL GUIDEWAYS

- Machining occurs as a result of a relative motion between the tool and the WP. Such a motion is a rotary, linear, or rectilinear one.
- Guideways are required to perform the necessary machine tool motion at a high level of accuracy under severe machining conditions.
- Generally guideways, therefore, control the movement of the different parts of the machine tool in all positions during machining and nonmachining times.
- Besides the accuracy requirements, ease of assembly, and economy in manufacturing guideways, the following features should be provided:
 - ✓ Accessibility for effective lubrication
 - ✓ Wear resistance, durability, and rigidity
 - ✓ Possibility of wear compensation
 - ✓ Restriction of motion to the required directions
 - ✓ Proper contact all over the sliding area
- Guideways are classified as sliding friction, rolling friction, and externally pressurized (Figure 2.11).



MACHINE TOOL GUIDEWAYS: SLIDING FRICTION GUIDEWAYS

- Sliding friction guideways consist of any one of or a combination of the flat, vee, dovetail, and cylindrical guideway elements.
- Flat circular guideways are used for guiding the rotating table of the vertical turning and boring machines.
- Figure 2.12 shows the different types of guideways that are normally used to guide sliding parts in the longitudinal directions.
- Holding strips may be provided to prevent the moving part from lifting or tilting by the operational forces.
- Scraping and the introduction of thin shims are used for readjustments that may be required to compensate wear of the sliding parts.

MACHINE TOOL GUIDEWAYS: SLIDING FRICTION GUIDEWAYS




FIGURE 2.12 Types of guideways: (a) vee, (b) flat, (c) dovetail, (d) cylinder, (e) cylindrical-cylindrical, and (f) cylindrical-flat.

MACHINE TOOL GUIDEWAYS: SLIDING FRICTION GUIDEWAYS

- Vee-shaped guideways are either male or female type, which are self-adjusting under the weight of the guided parts.
- The combination of two vee guideways has an unfavorable effect on the machining accuracy and is limited to guideways of relatively small distance between the two vees.
- Circular vee guideways carry the operational loads and provide self location for the rotating table.
- Dovetail guideways, shown in Figure 2.12c, are used separately or in a combination of half dovetail and flat guideways.
- Cylindrical guides, shown in Figure 2.12d, are either male or female type that must be accurately manufactured. They require special devices to adjust their working clearances.
- The column of the drilling machine is a typical example of the male type, while the sleeve of the drilling machine spindle is a female type.
- The combinations of cylindrical guideways are shown in Figures 2.12e (cylindrical–cylindrical) and 2.12f (cylindrical–flat).

MACHINE TOOL GUIDEWAYS: SLIDING FRICTION GUIDEWAYS

- For the sliding surfaces, the bulk of the load is carried on the metal-to-metal contact.
- The load carried by the lubricating oil film is very small.
- The localized pressures cause elastic or plastic deformation to the supporting asperities of the surface, which in turn results in an instability of the sliding motion usually known as the stick–slip effect.
- This phenomenon can be reduced or eliminated by the use of proper lubricants or through the introduction of externally pressurized guideways.
- Friction condition and, consequently, the wear of the guideways are affected by
 1. material properties of the fixed and moving element,
 2. surface dimensions of the guideways,
 3. acting pressure,
 4. accumulation of dirt, chip, and wear debris.

MACHINE TOOL GUIDEWAYS: SLIDING FRICTION GUIDEWAYS

- When the machine parts rub together, loss of material from one or both surfaces occurs, which in turn results in a change of the designed dimensions and geometry of the guideways system.
- Wear of guideways may be caused by the cutting action of the hard particles (adhesive wear), which is often accompanied by the oxidation of the wear debris that leads to additional abrasive wear.
- Wear of guideways can be minimized by
 1. minimizing the sliding surface roughness,
 2. increasing the hardness of the sliding surfaces,
 3. removing the abrasive wear particles from the guideways system
 4. reducing the pressure acting on the guiding surfaces.

MACHINE TOOL GUIDEWAYS: SLIDING FRICTION GUIDEWAYS

- Guideways are equipped with devices for initially adjusting and periodically compensating the working clearance.
- Clearance adjustment is accomplished by using suitable metallic strips, as shown in Figure 2.13.
- Guideways may be an integral part of the machine tool or mechanically secured to the bed by fastening or welding.
- In the first arrangement, the bed and the guideway are made from the same material, and flame or induction hardening is employed upon the guiding surfaces.
- In the mechanically secured guideways, separate steel guideways are secured to the CI beds, as shown in Figure 2.14a.

MACHINE TOOL GUIDEWAYS: SLIDING FRICTION GUIDEWAYS





FIGURE 2.13 Wear compensation in guideways: (a) flat and (b) dovetail guideways. F is the side force acting on the carriage.

MACHINE TOOL GUIDEWAYS: SLIDING FRICTION GUIDEWAYS




(a) Mechanically secured and (b) welded guideways.



MACHINE TOOL GUIDEWAYS: ROLLING FRICTION GUIDEWAYS

- In rolling friction guideways, rollers, needles, or balls are inserted between the moving parts to minimize the frictional resistance, which is kept constant irrespective of the traveling speed.
- Rolling friction guideways find wide applications in numerically controlled and medium-size machine tools in which the setting accuracy is decisive.
- Their expensive manufacturing, complicated construction and the short life of the rolling elements create problems.
- Rolling friction guideways are either open or closed.
- The open type (Figure 2.15) is used when the load acts downward, which makes this type self-adjusting for wear in the guideways.
- In the closed type, wear compensation requires adjusting elements.
- For long strokes, recirculating rolling elements (as shown in Figure 2.16) or ball or roller bearing guideways (Figure 2.17) are used to shorten the length of the slider.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 41





MACHINE TOOL GUIDEWAYS: ROLLING FRICTION GUIDEWAYS

- Circular rolling friction guideways find applications in high-speed vertical lathes. The size and the distribution of the load on the rolling elements and the deformation of the guideways are affected by:
 - 1. magnitude, distribution, and type of loading,
 - 2. stiffness of the rolling elements,
 - 3. manufacturing errors of the rolling elements,
 - 4. form error of the guideways,
 - 5. magnitude of preloading
 - 6. stiffness of the table, bed, fixture, and WP.

MACHINE TOOL GUIDEWAYS: EXTERNALLY PRESSURIZED GUIDEWAYS

- The load-carrying capacity and stiffness of ordinary lubricated guideways are excellent; however, their friction levels are undesirable.
- To overcome such a problem, externally pressurized guideways are used in which the sliding elements are separated by a thin film of pressurized fluid, as shown in Figure 2.18.
- Such an arrangement prevents contact between the sliding surfaces and hence avoids the occurrence of wear.
- The load-carrying capacity is independent of the sliding speed, and the reaction forces are distributed over the full bearing area.
- Externally pressurized guideways are ideal guideways in terms of stiffness, uniformity of travel, low friction, large damping, and better heat dissipation capacity.

MACHINE TOOL GUIDEWAYS: EXTERNALLY PRESSURIZED GUIDEWAYS




FIGURE 2.18 Externally pressurized guideways.

MACHINE TOOL GUIDEWAYS: EXTERNALLY PRESSURIZED GUIDEWAYS

- Generally, the service properties of machine tool guideways can be improved by
- 1. providing favorable frictional conditions, which can be achieved by using
 - a. combined sliding and rolling guides,
 - b. proper lubricants and materials for guideways
 - c. hydrostatic ways with high-rigidity oil film and automatic control systems,
- 2. providing adequate protection of guideways,
- 3. using optimal cross-section of slideways,
- 4. using optimal surface finishes.

MACHINE TOOL SPINDLES

- Machine tool spindles are used to locate, hold, and drive the tool or the WP.
- These spindles possess a high degree of rigidity, rotational accuracy, and wear resistance.
- Spindles of the general purpose machine tools are subjected to heavier loads compared with precision ones.
- In the former class of spindles, rigidity is the main requirement; in the second, the manufacturing accuracy is of the prime consideration.
- Spindles are normally made hollow and provided with an internal taper at the nose end to accommodate the center or the shank of the cutting tool (Figure 2.19).

MACHINE TOOL SPINDLES




FIGURE 2.19 Typical milling machine spindle.

MACHINE TOOL SPINDLES

- A thread can be added at the nose end to fix a chuck or a face plate.
- Medium-carbon steel containing 0.5% C is used for making spindles in which hardening is followed by tempering to produce a surface hardness of about 40 Rockwell (HRC).
- Low-carbon steel containing 0.2% C can also be carburized, quenched, and tempered to produce a surface hardness of 50–60 HRC.
- Spindles for high-precision machine tools are hardened by nitriding, which provides a sufficient hardness with the minimum possible deformation.
- Manganese steel is used for heavy-duty machine tool spindles.

MACHINE TOOL SPINDLES: SPINDLE BEARINGS

- Generally, machine tool spindle bearings must provide the following requirements:
 1. Minimum deflection under varying loads
 2. Accurate running under loads of varying magnitudes and directions
 3. Adjustability to obtain minimum axial and radial clearances
 4. Simple and convenient assembly
 5. Sufficiently long service
 6. Maximum temperature variation throughout the speed ranges
 7. Sufficient wear resistance


MACHINE TOOL SPINDLES: SPINDLE BEARINGS

- The forces acting on a machine tool spindle are the cutting force, which acts at the spindle nose, and the driving force, which acts in between the spindle bearings (Figure 2.20).
- The cutting force can be resolved into two components with respect to the spindle.
- The spindle bearings have to take radial and axial components of the cutting and driving forces.
- In this manner, when the machine tool spindle is mounted at two points, the bearing at one point takes the axial component besides the reaction of the radial component, while the other takes only the reaction of the radial component.
- The bearings that carry the axial component should prevent the axial movement of the spindle under the effect of the cutting and driving forces (fixed bearing).
- The other bearing (floating bearing) provides only a radial support and provides axial displacement due to differential thermal expansion of the spindle shaft and the housing.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 53

MACHINE TOOL SPINDLES: SPINDLE BEARINGS



Forces acting on machine tool spindles.

• Lecture 2: Basic Elements and Mechanisms


Dr. Parviz Kahhal • 54

MACHINE TOOL SPINDLES: SPINDLE BEARINGS

- The arrangement shown in Figure 2.21a is used in most high-speed machine tools because the free length of the spindle (from nose to the fixed bearing) is limited, which minimizes nose deflection.
- Additionally, the effect of differential thermal expansion of the spindle and spindle housing acts toward the floating (rear) end, which in turn reduces the axial displacements of the spindle nose.
- Figure 2.22 shows typical spindle bearing mounting arrangements. Figure 2.23 presents a machine tool spindle with the fixed front bearing while the rear end axially slides at the outer race of the roller bearing.
- The various considerations in the selection of bearings are
 1. direction of load relative to the bearing axial,
 2. intensity of load,
 3. speed of rotation,
 4. thermal stability,
 5. stiffness of the spindle shaft
 6. class of accuracy of the machine.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 55



Fixed and floating bearing arrangements: (a) fixed front, (b) fixed rear, and (c) fixed middle.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 56

MACHINE TOOL SPINDLES: SPINDLE BEARINGS




FIGURE 2.22 Typical spindle-bearing arrangements. (From Browne, J. W., *The Theory of Machine Tools, Book-1*, Cassell and Co. Ltd., London, 1965.)

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 57

MACHINE TOOL SPINDLES: SPINDLE BEARINGS




FIGURE 2.23 Typical machine tool spindle. (From Koenigsberger, F., *Berechnungen, Konstruktionsgrundlagen und Bauelemente spanender Werkzeugmaschinen*, Springer, Berlin, 1961. With permission.)

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 58

MACHINE TOOL SPINDLES:

SLIDING FRICTION SPINDLE BEARING

- Rolling bearings are used at a speed and diameter range of $n \cdot d \leq 2 \times 10^5$ where n is the spindle rotational speed in revolutions per minute and d is the diameter of the spindle in millimeters.
- At higher running speeds, the bearing life is reduced due to the gyratory action, especially in bearings that take combined loads.
- At high spindle speeds, as in case of grinding, sliding friction (journal) bearings that have high damping capacity compared with rolling bearings are used.
- Their load-carrying capacity increases as the spindle speed increases due to the hydrodynamic action created within the bearing.
- For an optimum performance, the radial clearance between journal and bearing should be properly maintained, as it affects bearing friction, load-carrying capacity, and the efficiency of heat dissipation of the bearing.

MACHINE TOOL SPINDLES:

SLIDING FRICTION SPINDLE BEARING

- The main types of sliding friction bearings include the following:
- 1. Sliding bearing with radial play adjustment using segments that can be adjusted radially to control the clearance.
- 2. Bearing with axial play adjustment, in which a bush with a cylindrical bore and external taper has a slot along its length and is made to fit in a taper hole in the housing. When the bush slides axially, through two opposing nuts, on the two ends of the bush, radial play can be finely adjusted and controlled (Figure 2.25).


MACHINE TOOL SPINDLES:

SLIDING FRICTION SPINDLE BEARING


- 3. Mackensen bearing is used in highly accurate machine tool spindles, running at extremely high speeds, under limited applied load. As shown in Figure 2.26, an elastic bearing bush is supported at three points in the housing. This bush has nine equally spaced axial slots along its circumference. When the shaft is running, the bush deforms into a triangular shape, and three wedge-shaped oil pockets are formed, which constitute the load-carrying parts of the bearing.
- 4. Hydrodynamic multipad spindle bearing of high radial and axial thrust capacity, high stiffness, and practically no clearance during operation.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 61



MACHINE TOOL SPINDLES: SLIDING FRICTION SPINDLE BEARING



26 Mackensen bearing.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 63

MACHINE TOOL SPINDLES: SLIDING FRICTION SPINDLE BEARING


- Sliding bearing materials should have high compressive strength to withstand the bearing pressure, low coefficient of friction, and high thermal conductivity.
- It should possess high wear resistance and maintain a continuous oil film.
- The various sliding bearing metals include:
 1. copper base bearing metals (85% Cu, 10% Sn, 5% Zn), which are used for heavy loads,
 2. tin base bearing (babbitt) metals (85% Sn, 10% Sb, 5% Cu), which are used for higher loads,
 3. lead base bearing metals (10–30% Pb, 10–15% Sb, and the rest is copper), which are used for light loads,
 4. cadmium base bearing metals (95% Cd and a very small amount of iridium) which have higher compressive strength and more favorable properties at higher temperatures.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 64

MACHINE TOOL DRIVES

- To obtain a machined part by a machine tool, coordinated motions must be imparted to its working members.
- These motions are either primary (cutting and feed) movements, which removes the chips from the WP or auxiliary motions that are required to prepare for machining and ensure the successive machining of several surfaces of one WP or a similar surface of different WPs.
- Principal motions may be either rotating or straight reciprocating.
- In some machine tools, this motion is a combination of rotating and reciprocating motions.
- Feed movement may be continuous (lathes, milling machine, drilling machine) or intermittent (planers).
- As shown in Figure 2.27, stepped motions are obtained using belting or gearing.
- Stepless speeds are achieved by mechanical, hydraulic, and electrical methods.



MACHINE TOOL DRIVES: STEPPED SPEED DRIVES: Belting


- The belting system, shown in Figure 2.28, is used to produce four running rotational speeds n_1 , n_2 , n_3 , and n_4 .
- It is cheap and absorbs vibrations.
- It has the limitation of the low-speed changing, slip, and the need for more space.
- Based on the driver speed n_1 , the following speeds can be obtained in a decreasing order:

$$n_1 = n \frac{d_1}{d_5}$$

$$n_2 = n \frac{d_2}{d_6}$$

$$n_3 = n \frac{d_3}{d_7}$$


- This type is commonly used for grinding and bench-type drilling machines.



MACHINE TOOL DRIVES: STEPPED

SPEED DRIVES: Pick-Off Gears

- Pick-off gears are used for machine tools of mass and batch production (automatic and semiautomatic machines, special-purpose machines, and so on) when the changeover from job to job is comparatively rare.
- Pick-off gears may be used in speed or feed gearboxes.
- As shown in Figure 2.29, the change of speed is achieved by setting gears A and B on the adjacent shafts.
- As the center distance is constant, correct gear meshing occurs if the sum of teeth of gears A and B is constant.



MACHINE TOOL DRIVES: STEPPED SPEED DRIVES: Gearboxes

- Machine tools are characterized by their large number of spindle speeds and feeds to cope with the requirements of machining parts of different materials and dimensions using different types of cutting tool materials and geometries.
- The cutting speed is determined on the bases of the cutting ability of the tool used, surface finish required, and economical considerations.
- A wide variety of gearboxes utilize sliding gears or friction or jaw coupling.
- The selection of a particular mechanism depends on the purpose of the machine tool, the frequency of speed change, and the duration of the working movement.

MACHINE TOOL DRIVES: STEPPED SPEED DRIVES: Gearboxes

- The advantage of a sliding gear transmission is that it is capable of transmitting higher torque and is small in radial dimensions.
- Among the disadvantages of these gearboxes is the impossibility of changing speeds during running.
- Clutch-type gearboxes require small axial displacement needed for speed changing, less engagement force compared with sliding gear mechanisms, and therefore can employ helical gears.

MACHINE TOOL DRIVES: STEPPED SPEED DRIVES: Gearboxes

- The extreme spindle speeds of a machine tool main gearbox n_{\max} and n_{\min} can be determined by

$$n_{\max} = \frac{1000V_{\max}}{\pi d_{\min}}$$

$$n_{\min} = \frac{1000V_{\min}}{\pi d_{\max}}$$

V_{\max} = maximum cutting speed (m/min) used for machining the most soft and machinable material with a cutting tool of the best cutting property

V_{\min} = minimum cutting speed (m/min) used for machining the hardest material using a cutting tool of the lowest cutting property or the necessary speed for thread cutting

d_{\max}, d_{\min} = maximum and minimum diameters (mm) of WP to be machined

MACHINE TOOL DRIVES: STEPPED SPEED DRIVES: Gearboxes

- The speed range R_n becomes

$$R_n = \frac{n_{\max}}{n_{\min}} = \frac{V_{\max}}{V_{\min}} \cdot \frac{d_{\max}}{d_{\min}} = R_v \cdot R_d$$

R_v = cutting speed range

R_d = diameter range

MACHINE TOOL DRIVES: STEPPED

SPEED DRIVES: Gearboxes

- In case of machine tools having rectilinear main motion (planers and shapers), the speed range R_n is dependent only on R_v .
- For other machine tools, R_n is a function of R_v and R_d , large cutting speeds and diameter ranges are required.
- Generally, when selecting a machine tool, the speed range R_n is increased by 25% for future developments in the cutting tool materials.
- Table 2.4 shows the maximum speed ranges in modern machine tools.

MACHINE TOOL DRIVES: STEPPED

SPEED DRIVES: Gearboxes

TABLE 2.4

Speed Range for Different Machine Tools

Machine	Range
Numerically controlled lathes	250
Boring	100
Milling	50
Drilling	10
Surface grinding	4

MACHINE TOOL DRIVES: STEPPED SPEED DRIVES:

Stepping of Speeds According to Arithmetic Progression


- Let n_1, n_2, \dots, n_z be arranged according to arithmetic progression. Then

$$n_1 - n_2 = n_3 - n_2 = \text{constant}$$

- The sawtooth diagram in such a case is shown in Figure 2.30. Accordingly, for an economical cutting speed v_0 , the lowest speed v_1 is not constant; it decreases with increasing diameter.
- Therefore, the arithmetic progression does not permit economical machining at large diameter ranges.
- The main disadvantage of such an arrangement is that the percentage drop from step to step δ_n decreases as the speed increases.
- Thus the speeds are not evenly distributed and more concentrated and closely stepped, in the small diameter range than in the large one.
- Stepping speeds according to arithmetic progression are used in Norton gearboxes or gearboxes with a sliding key when the number of shafts is only two.

MACHINE TOOL DRIVES: STEPPED SPEED DRIVES:

Stepping of Speeds According to Arithmetic Progression



Speed stepping according to arithmetic progression.


MACHINE TOOL DRIVES: STEPPED SPEED DRIVES:

Stepping of Speeds According to Geometric Progression

- As shown in Figure 2.31, the percentage drop from one step to the other is constant, and the absolute loss of economically expedient cutting speed Δv is constant all over the whole diameter range.
- The relative loss of cutting speed $\Delta v_{max}/v_0$ is also constant.
- Geometric progression, therefore, allows machining to take place between limits v_0 and v_u independent of the WP diameter, where v_0 is the economical cutting speed and v_u is the allowable minimum cutting speed.
- Now suppose that $n_1, n_2, n_3, \dots, n_z$ are the spindle speeds. According to the geometric progression,

$$\frac{n_2}{n_1} = \frac{n_3}{n_2} = \varphi$$

- where φ is the progression ratio.



MACHINE TOOL DRIVES: STEPPED SPEED DRIVES:

Stepping of Speeds According to Geometric Progression

- The spindle speeds can be expressed in terms of the minimal speed n_1 and progression ratio ϕ .

$$\begin{array}{cccccc} n_1 & n_2 & n_3 & n_4 & n_z \\ n_1 & n_1\phi & n_1\phi^2 & n_1\phi^3 & n_1\phi^{z-1} \end{array}$$

- Hence, the maximum spindle speed n_z is given by

$$n_z = n_1\phi^{z-1}$$

- where z is the number of spindle speeds, therefore,

$$\phi = \sqrt[z-1]{\frac{n_z}{n_1}} = \sqrt[z-1]{R_n} = (R_n)^{1/(z-1)}$$

- from which

$$z = \frac{\log R_n}{\log \phi} + 1$$

MACHINE TOOL DRIVES: STEPPED SPEED DRIVES:

Stepping of Speeds According to Geometric Progression

- Progression ratios are standardized according to ISO standards in such a way as to allow standard speeds and feeds, including full load induction motor speeds of 2800, 1400, and 710 rpm to be used.
- Table 2.5 shows the standard values of ϕ according to ISO/R229. Similarly, machine tool speeds are standardized according to ISO/R229.
- Such speeds enable the direct drive of machine tool spindles using induction motors with changing poles.
- The full load speeds of induction motors are 236, 280, 322, 472, 200, 710, 920, 1400, and 2800 rpm.
- Tables 2.6 and 2.7 show the standard speeds and feeds
- according to ISO/R229.

MACHINE TOOL DRIVES: STEPPED SPEED DRIVES:

Stepping of Speeds According to Geometric Progression

TABLE 2.5

Standard Values of Progression Ratio ϕ According to ISO/R229 and Deutsches Institut für Normung (DIN) 323

Basic and Derived Series	Standard Value	Accurate Value	Percentage Drop	Application
R20	$20\sqrt{10} = 1.12$	1.1221	10	Seldom used
R20/2	$(20\sqrt{10})^2 = 1.26$	1.258	20	Machines of large z
R20/3	$(20\sqrt{10})^3 = 1.4$	1.4125	30	Machines of large R_n
R20/4	$(20\sqrt{10})^4 = 1.6$	1.5849	40	and small z
R20/6	$(20\sqrt{10})^6 = 2.0$	1.9953	50	Drilling machines

Note: z , Number of speeds; R_n , speed range.

TABLE 2.6

Standard Speeds According to ISO/R229 and DIN 804

Accurate Value (rpm)	Basic Series			Derived Series		Limiting Values	Considering 2% Mechanical Tolerance
	R20 $\phi = 1.12$	R20/2 $\phi = 1.25$	R20/3 $\phi = 1.4$	R20/4 1400-800 $\phi = 1.6$	R20/6 2800 $\phi = 2.0$		
100	100					98	102
112.2	112		11.2		112	110	114
125			125			123	128
141.25	140	140		1400	140	1400	138
158.49	160		16			155	162
177.83	180	160		180	180	180	174
199.52	200			2000			193
223.87	224	224	22.4		22.4	219	228
251.19	250			250		246	256
281.84	280	280		2800	280	2800	276
316.23	315		31.5			310	323
354.81	355	355		355		355	348
398.11	400			4000		390	406
446.68	450	450	45		450	448	456
501.19	500			500		491	511
562.34	560	560		5600	560	5600	551
630.96	630		63			618	643
707.95	710	710		710	710	710	722
794.33	800			8000		778	810
891.25	900	900	90		900	900	873
1000	1000			1000		980	1020

TABLE 2.7
Standard Feeds According to ISO/R229 and DIN 803

Nominal Values					
R20	R20/2	R20/3 ...1...		R20/4	R20/6 ...1...
$\varphi = 1.12$	$\varphi = 1.25$	$\varphi = 1.4$		$\varphi = 1.6$	$\varphi = 2.0$
1.00	1.0		1.0	1.0	1.0
1.12				11.2	
1.25	1.25	0.125			0.125
1.40			1.4		
1.60	1.6			16	
1.80		0.18			16
2.00	2.0		2.0		2.0
2.24				20	
2.50	2.5	0.25		2.5	0.25
2.80			2.8		
3.15	3.15			31.5	
3.55		0.355			31.5
4.00	4.0		4.0	4	4.0
4.50				45	
5.00	5.0	0.5			0.5
5.60			5.6		
6.30	6.3			63	63
7.10		0.71			
8.00	8.0		8.0		8.0
9.00				90	
10.00	10.0		1000	10	

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 85

MACHINE TOOL DRIVES: STEPPED SPEED DRIVES:

Stepping of Speeds According to Geometric Progression

- **Illustrative Example**

- The following speeds form a geometric progression. Find the progression ratio and the percentage increase in the speed series.

n_1 (rpm)	n_2 (rpm)	n_3 (rpm)	n_4 (rpm)	n_5 (rpm)	n_6 (rpm)
14	18	22.4	28	35.2	45

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 86

MACHINE TOOL DRIVES: STEPPED SPEED DRIVES:

Stepping of Speeds According to Geometric Progression

- Solution

$$\varphi = \frac{n_2}{n_1} = \frac{18}{14} = 1.25$$

- Or

$$\varphi = \sqrt[5]{\frac{45}{14}} = 1.25$$

- The percentage increase in speed δ_n

$$\delta_n = \frac{n_2 - n_1}{n_1} = \frac{\varphi n_1 - n_1}{n_1} = (\varphi - 1) \times 100$$

$$\delta_n = (1.25 - 1) \times 100 = 25\%$$

MACHINE TOOL DRIVES: STEPPED SPEED DRIVES:

Stepping of Speeds According to Geometric Progression

- **Illustrative Example**

- Given $n_1 = 2.8$ rpm, $n_z = 31.50$ rpm, and $\varphi = 1.41$, calculate the speed range R_n and the number of speeds z .
- Solution

$$R_n = \frac{n_z}{n_1} = \frac{31.50}{2.8} = 11.2$$


$$\varphi = (R_n)^{1/(z-1)} \quad z = \frac{\log R_n}{\log \varphi} + 1$$

$$z = \frac{\log 11.2}{\log 1.41} + 1 = 8$$

MACHINE TOOL DRIVES:

STEPPED SPEED DRIVES: Feed Gearboxes

- Feed gearboxes are designed to provide the feed rates required for the machining operation.
- The values of feed rates are determined by the specified surface finish, tool life, and the rate of material removal.
- The classification of feed gearboxes according to the type of mechanism used to change the rate of feed is as follows:
- 1. Feed gearboxes with pick-off gears. Used in batch-production machine tools with infrequent changeover from job to job, such as automatic, semiautomatic, single-purpose, and special-purpose machine tools. These gearboxes are simple in design and are similar to those used for speed changing (Figure 2.29).



Pick-off gears.

MACHINE TOOL DRIVES:

STEPPED SPEED DRIVES: Feed Gearboxes


- 2. Feed gearboxes with sliding gears. These gearboxes are widely used in general-purpose machine tools, transmit high torques, and operate at high speeds. Figure 2.36 shows a typical gearbox that provides four different ratios. Accordingly, gears Z_2 , Z_4 , Z_6 , and Z_8 are keyed to the drive shaft and mesh, respectively, with gears Z_1 , Z_3 , Z_5 , and Z_7 , which are mounted freely on the driven key shaft. The sliding gear engages any gear on the driven shaft. The engaged gear transmits the motion to the driven shaft while the rest of the gears remain idle.
- The main drawbacks of such feed boxes are the power loss and wear occurring due to the rotation of idle gears and insufficient rigidity of the sliding key shaft. Feed boxes with sliding gears are used in small- and medium-size drilling machines and turret lathes.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal © 91

MACHINE TOOL DRIVES:

STEPPED SPEED DRIVES: Feed Gearboxes



Feed gearbox with sliding gears.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal © 92


MACHINE TOOL DRIVES:

STEPPED SPEED DRIVES: Feed Gearboxes

- 3. Norton gearboxes. These gearboxes provide an arithmetic series of feed steps that is suitable for cutting threads and so are widely used in engine lathe feed gearboxes as shown in Figure 2.37.

MACHINE TOOL DRIVES:

STEPPED SPEED DRIVES: Feed Gearboxes



Norton gearbox.

MACHINE TOOL DRIVES: STEPPED SPEED DRIVES:

Preselection of Feeds and Speeds

- Preselection mechanisms in machine tools are used to select the speeds and feeds for the next machining operation during the machining time of the current operation. Once the current operation is finished, the selected speed and feed are automatically switched on with the press of a button.
- The main advantage of such a system in machine tools is to save the significant secondary time normally used for selecting the speeds and feeds at the end of each machining operation.
- Consequently, the total production time is reduced. The adoption of preselection mechanisms is justified whenever the speeds and feeds of the machine tool are frequently changed.

MACHINE TOOL DRIVES: STEPLESS SPEED DRIVES:

Mechanical Stepless Drives

- Infinitely variable speed (stepless) drives provide output speeds, forming infinitely variable ratios to the input ones.
- Such units are used for main as well as feed drives to provide the most suitable speed or feed for each job, thereby reducing the machining time.
- They also enable machining to be achieved at a constant cutting speed, which leads to an increased tool life and ensures uniform surface finish.
- The easy and smooth changing of the speed or feed, without stopping the machine, results in an appreciable reduction in the production time that raises the productivity of the machine tool.

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives

- Stepless speed drives may be mechanical, hydraulic, or electric.
- The selection of the suitable drive depends on the purpose of the machine tool, power requirements, speed range ratio, mechanical characteristics of the machining operation, and cost of the variable speed unit.
- In most stepless drives, the torque transmission is not positive. Their operation involves friction and slip losses.
- However, they are more compact, less expensive, and quieter in operation than the stepped speed control elements.

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:


Mechanical Stepless Drives

- Mechanical stepless drives include the following types:
 1. Friction Stepless Drive
 2. Kopp Variator
 3. Toroidal and Reeves Mechanisms
 4. Positive Infinitely Variable Drive

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Friction Stepless Drive

- Figure 2.39 shows the disk-type friction stepless mechanism.



• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 99

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Friction Stepless Drive

- Accordingly, the drive shaft rotates at a constant speed n_1 as well as the friction roller of diameter d .
- The output speed of the driven shaft rotates at a variable speed n_2 that depends on the instantaneous diameter D .
- Because

$$n_1 d = n_2 D$$

- hence

$$n_2 = n_1 \frac{d}{D}$$

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 100

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Friction Stepless Drive

- The diameter ratio d/D can be varied in infinitely small steps by the axial displacement of the friction roller.
- If the friction force between the friction roller and the disk is F ,

$$F = \frac{\text{input torque } (T_1)}{\text{input radius } (d/2)} = \frac{\text{output torque } (T_2)}{\text{output radius } (D/2)}$$

- If the power, contact pressure, transmission force, and efficiency are constant, the output torque T_2 is inversely proportional to the speed of the output shaft n_2 .

$$T_2 \propto T_1 \frac{n_1}{n_2}$$

- Due to the small contact area, a certain amount of slip occurs, which makes this arrangement suitable for transmitting small torques and is limited to reduction ratios not more than 1:4.

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Kopp Variator




FIGURE 2.40 Kopp stepless speed mechanism: (a) $n_2 < n_1$, (b) $n_2 = n_1$, and (c) $n_2 > n_1$.

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Kopp Variator

- In the Kopp variator, shown in Figure 2.40, the drive balls (4) mounted on inclinable axes (3) run in contact with identical, effective radii $r_1 = r_2$, and drive cones (1 and 2) are fixed on coaxial input and output shafts.
- When the axes of the drive balls (3) are parallel to the drive shaft axes, the input and output speeds are the same.
- When they are tilted, r_1 and r_2 change, which leads to the increase or decrease of the speed.
- Using Kopp mechanism, a speed range of 9:1, efficiency of higher than 80% and 0.25–12 hp capacity are obtainable.

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Toroidal and Reeves Mechanisms





FIGURE 2.41 Toroidal stepless speed transmission: (a) $n_2 < n_1$, (b) $n_2 = n_1$, and (c) $n_2 > n_1$.

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Toroidal and Reeves Mechanisms



• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 105

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Toroidal and Reeves Mechanisms


- Figure 2.42 shows the Reeves variable speed transmission, which consists of a pair of pulleys connected by a V-shaped belt; each pulley is made up of two conical disks.
- These disks slide equally and simultaneously along the shaft and rotate with it. To adjust the diameter of the pulley, the two disks on the shaft are made to approach each other so that the diameter is increased or decreased.
- The ratio of the driving diameter to the driven one can be easily changed and, therefore, any desired speed can be obtained without stopping the machine.
- Drives of this type are available with up to 8:1 speed range and 10 hp capacity.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 106

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Positive Infinitely Variable Drive



Positive infinitely variable drive.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 107

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Positive Infinitely Variable Drive

- Figure 2.43 shows a positive torque transmission arrangement that consists of two chain wheels, each of which consists of a pair of cones that are movable along the shafts in the axial direction.
- The teeth of the chain wheels are connected by a special chain. By rotating the screw, the levers get moved thus changing the location of the chain pulleys, and hence the speed of rotation provides a speed ratio of up to 6 and is available with power rating up to 50 hp.
- The use of infinite variable speed units in machine tool drives and feed units is limited by their higher cost and lower efficiency or speed range.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 108

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Electrical Stepless Speed Drive

- Figure 2.44 shows the Leonard set, which consists of an induction motor that drives the direct current generator and an exciter (E).
- The dc generator provides the armature current for the dc motor, and the exciter provides the field current; both are necessary for the dc motors that drive the machine tool.
- The speed control of the dc motor takes place by adjusting both the armature and the field voltages by means of the variable resistances A and F, respectively.

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Electrical Stepless Speed Drive




FIGURE 2.44 Leonard set (electrical stepless speed drive).

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Electrical Stepless Speed Drive

- By varying the resistance A , the terminal voltage of the dc generator and hence the rotor voltage of the dc motor can be adjusted between zero and a maximum value.
- The Leonard set has a limited efficiency: it is large, expensive, and noisy.
- Nowadays, dc motors and thyrestors that permit direct supply to the dc motors from an alternating current (ac) mains are available and, therefore, the Leonard set can be completely eliminated.
- Thyrestor feed drives can be regulated such that the system offers infinitely variable speed control.

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Hydraulic Stepless Speed Drive

- The speeds of machine tools can be hydraulically regulated by controlling the oil discharge circulated in a hydraulic system consisting of a pump and hydraulic motor, both of the vane type, as shown in Figure 2.45.
- This is achieved by changing either the eccentricity of the pump e_p or the eccentricity of the hydraulic motor e_m or both.
- The vane pump running approximately at a constant speed delivers the pressurized oil to the vane type hydraulic motor, which is coupled to the machine tool spindle.
- To change the direction of rotation of the hydraulic motor, the reversal of the pump eccentricity is preferred.
- Speed control in hydraulic circuits can be accomplished by throttling the quantity of fluid flowing into or out of the hydrocylinders or hydromotor.

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:

Mechanical Stepless Drives: Hydraulic Stepless Speed Drive




FIGURE 2.45 Hydraulic stepless speed drive.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 113

MACHINE TOOL DRIVES:STEPLESS SPEED DRIVES:


Mechanical Stepless Drives: Hydraulic Stepless Speed Drive

- The advantages of the hydraulic systems are as follows:
 1. Has a wide range of speed variation
 2. Changes in the magnitude and direction of speed can be easily performed
 3. Provides smooth and quiet operation
 4. Ensures self-lubrication
 5. Has automatic protection against overloads
- The major drawback to a hydraulic system is that the operation of the hydraulic drive becomes unstable at low speeds.
- Additionally, the oil viscosity varies with temperature and may cause fluctuations in feed and speed rates.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 114

**MACHINE TOOL DRIVES:
PLANETARY TRANSMISSION**



Planetary transmission.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 115

MACHINE TOOL DRIVES:

PLANETARY TRANSMISSION

- Figure 2.46 shows a planetary transmission with bevel gears that is widely used in machine tools.
- Accordingly, any two members may be the driving members, while the third one is the driven member.
- The differential contains central gears Z_1 and Z_4 , and satellites Z_2 and Z_3 (an additional wheel) rotated by worm gear 2.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 116

MACHINE TOOL DRIVES:

PLANETARY TRANSMISSION

- The differential can operate as follows (Chernov, 1984):
- 1. Z_4 is a driving member, the carrier is a driven member, and worm gear 2 is stationary.
- 2. The carrier is a driving member, gear Z_4 is a driven member, and worm gear 2 is stationary.
- 3. Gear wheel Z_1 is a driving member (rotated by worm gear 2), gear wheel Z_4 is a driven member, and the carrier is fixed.
- 4. The carrier is a driving member, so is gear Z_1 , and gear wheel Z_4 is a driven member.
- 5. Gear wheels Z_1 and Z_4 are driving members and the carrier is a driven member.

MACHINE TOOL DRIVES:

PLANETARY TRANSMISSION

- The principal relationship between axes speed is described by Willis formula, with $Z_2 = Z_3$ and $Z_1 = Z_4$, as follows:

$$i = \frac{n_4 - n_0}{n_1 - n_0} = \frac{Z_2 Z_1}{Z_4 Z_3} = -1$$

where

i = conversion ratio

n_0 = speed of carrier rotation

n_1, n_2 = rotational speeds of Z_1 and Z_4 , respectively.

- The minus sign in the previous equation indicates that gear wheels Z_1 and Z_4 rotate in opposite direction when the carrier is stationary.

MACHINE TOOL MOTORS

- Most of machine tool drives operate on standard three-phase 50 Hz, 400/440 V ac supply.
- The selection of motors for machine tools depends on the following:
 1. Motor power
 2. The power supply used (ac/dc)
 3. Electrical characteristics of the motor
 4. Mechanical features that include mounting, transmission of drive, noise level, and the type of cooling
 5. Overload capacity

MACHINE TOOL MOTORS

- Squirrel-cage induction motors are the most popular due to their simplicity, robustness, availability with a wide range of operating characteristics, and low cost.
- Alternating current (ac) motors can provide infinitely variable speed over a wide range; however, their cost is high.
- Direct current (dc) shunt motors with field and armature control are commonly used for the main drives.
- For traverse drives, dc series or compound wound motors are preferred.
- Table 2.8 shows the different machine tool motors recommended for machine tools (Nagpal, 1996).

TABLE 2.8
Machine Tool Motors

Machine Tool	Types of Motor
Lathe	
Main drive and traverse drive	Multispeed squirrel cage Adjustable-speed dc
Traverse drive	dc series High-slip squirrel cage
Shapers and slotters	Constant-speed squirrel cage
Planers	Multispeed squirrel cage dc adjustable voltage
Drilling machines	Constant-speed squirrel cage dc shunt motor
Milling machines	Squirrel cage dc shunt motor
Power saws	Constant-speed squirrel cage
Grinding machines	
Wheel	Constant-speed squirrel cage Adjustable-speed dc
Traverse	Constant-speed squirrel cage

Source: Nagpal, G.R., in *Machine Tool Engineering*, Khanna Publishers, Delhi, India, 1999.

REVERSING MECHANISMS

- Movements of machine tool elements can be reversed by mechanical, electrical, and hydraulic devices.
- Among these are the mechanisms with spur gears and bevel gears.
- Figure 2.47 shows the reversing mechanisms with sliding spur gears (a) and those with fixed gears and clutches (b).
- Figure 2.47 also shows the reversing mechanism with bevel gears and a double-claw clutch (c).
- Hydraulic reversal of motion is effected by redirection of the oil delivered to an operative cylinder using a directional control valve, and electrical reversal is achieved by changing the direction of the drive motor rotation.

REVERSING MECHANISMS




FIGURE 2.47 Reversing mechanisms: (a) tumbler yoke gear, (b) spur gear with clutch, and (c) bevel gear with clutch.

COUPLINGS AND BRAKES

- Shaft couplings are used to fasten together the ends of two coaxial shafts. Permanent couplings cannot be disengaged while clutches engage and disengage shafts in operation.
- Safety clutches avoid the breakdown of the engaging mechanisms due to sharp increase in load, while overrunning clutches transmit the motion in only one direction.
- Figure 2.48 shows permanent couplings.
- Figure 2.49 shows a typical claw clutch (a) and a toothed clutch (b). These two clutches cannot be engaged when the difference between the speeds of shafts is high.
- However, a friction clutch (c) can be engaged regardless of the speeds of its two members.
- Additionally, they can slip in case of overloading. Other types of clutches include friction multidisk, contactless magnetic, or hydraulic clutch (Chernov, 1984).

COUPLINGS AND BRAKES




FIGURE 2.48 (a) Flanged coupling and (b) Oldham coupling.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 125




FIGURE 2.49 (a) Claw clutch, (b) toothed clutch, and (c) friction clutch. (From Chernov, N., *Machine Tools*, Mir Publishers, Moscow, 1975. With permission.)

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 126

COUPLINGS AND BRAKES

- Brakes are used in machine tools to quickly slow or completely stop their moving parts.
- This step can be performed using mechanical, electrical, or hydraulic (or a combination of these) devices.
- Figure 2.50 shows the shoe brake in which shoes (1 and 6) are connected by a rod (3), whose length is controlled by a nut (2) that controls the clearance between the shoes and the pulley (7).
- Braking is achieved by pressing the shoe against the pulley by an arm (4) driven by the brake actuator (5).
- Band brakes operate frequently by electromagnetic or solenoid actuators.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 127

COUPLINGS AND BRAKES




FIGURE 2.50 Shoe brake. (From Chernov, N., *Machine Tools*, Mir Publishers, Moscow, 1975. With permission.)

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 128

COUPLINGS AND BRAKES

- In a multiple-disk friction brake, shown in Figure 2.51, when the shaft sleeve (3) is moved to the left, it engages with its lever (2), which, in turn, compresses the clutch disks, thereby engaging the clutch.
- For braking, the sliding sleeve (3) is moved to the right, disengaging the clutch (1) and engaging the friction brake (4).

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 129

COUPLINGS AND BRAKES




FIGURE 2.51 Friction brake. (From Chernov, N., *Machine Tools*, Mir Publishers, Moscow, 1975. With permission.)

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 130

RECIPROCATING MECHANISMS: QUICK-RETURN MECHANISM

- Ruled flat surfaces are machined on the shaping or planing machines by the combined reciprocating motion and the side feed of the tool and WP.
- Figure 2.52 shows the quick-return mechanism of the shaper machine.
- Accordingly, the length of the stroke is controlled by the radial position of the crank pin and sliders A and B.
- The time taken for the crank pin to move through the angle corresponding to the cutting stroke α is less than that of the noncutting stroke β (the usual ratio is 2:1).
- Velocity curves for the cutting and reverse strokes are shown in Figure 2.52. The maximum speed occurs when the link is vertical.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 131

RECIPROCATING MECHANISMS: QUICK-RETURN MECHANISM




FIGURE 2.52 The quick-return mechanism.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 132

RECIPROCATING MECHANISMS:

QUICK-RETURN MECHANISM

- The speed of the link at point P for a given stroke length L will be that at the corresponding crank radius r , hence, the cutting speed v_c at point P_1 is

$$v_c = 2\pi r n \frac{l}{y+r} \text{ m/min}$$

where

n = number of strokes per minute

l = length of crank arm (constant)

RECIPROCATING MECHANISMS:

QUICK-RETURN MECHANISM

- Similarly, the maximum reverse speed v_r is given by the following equation:

$$v_r = 2\pi r n \frac{l}{y-r} \text{ m/min}$$

- In terms of the stroke length for maximum radius using similar triangles OBA and OCD

$$\frac{OD}{OA} = \frac{DC}{AB}$$

$$\frac{l}{y} = \frac{L}{2r}$$

RECIPROCATING MECHANISMS: QUICK-RETURN MECHANISM

- Hence

$$v_c = \pi n \left[\frac{lL}{l + L/2} \right]$$

- And

$$v_r = \pi n \left[\frac{lL}{l - L/2} \right]$$

- therefore, the speed ratio, Q

$$Q = \frac{V_r}{V_c} = \frac{2l + L}{2l - L}$$

RECIPROCATING MECHANISMS: QUICK-RETURN MECHANISM

- **Example**

In the slotted arm quick-return mechanism of the shaping machine, the maximum quick-return ratio is 3/2 and the stroke length is 400 mm. Calculate the length of the slotted arm. Calculate the maximum quick-return ratio if the stroke length is 180 mm.

RECIPROCATING MECHANISMS: QUICK-RETURN MECHANISM

- **Solution**

- The quick-return ratio Q

$$Q = \frac{V_r}{V_c} = \frac{2l + L}{2l - L}$$

$$Q = \frac{3}{2} = \frac{2l + 400}{2l - 400}$$

$$l = 1200 \text{ mm}$$


- The quick-return ratio Q, for L = 180 mm

$$Q = \frac{2 \times 1200 + 180}{2 \times 1200 - 180} = 1.11$$

RECIPROCATING MECHANISMS: WHITWORTH MECHANISM

- This arrangement is shown in Figure 2.53; when AB rotates, it drives CE about D by means of the slider F so that G moves horizontally along MN. AB moves through an angle $(360^\circ - \alpha)$ while CE moves through 180° , which is less than $360^\circ - \alpha$.
- Also, the crank moves through a while CE moves through 180° , which is greater than α .
- Hence, with a uniformly rotating crank, the link moves through one-half of its revolution more quickly than the other. The angle α is used for the return stroke.

RECIPROCATING MECHANISMS: WHITWORTH MECHANISM



Whitworth quick-return mechanism.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 139

RECIPROCATING MECHANISMS: WHITWORTH MECHANISM

- Hence

$$\frac{\text{Time for cutting stroke}}{\text{Time for return stroke}} = \frac{360 - \alpha}{\alpha}$$

- The stroke can be changed by altering the radius DE, with the angle α being unchanged.
- Provided that the fixed center D lies on the line of movement of G, the ratio of the cutting speed to the return speed lies between 1:2 and 1:2.5.

• Lecture 2: Basic Elements and Mechanisms

Dr. Parviz Kahhal • 140

RECIPROCATING MECHANISMS:

HYDRAULIC RECIPROCATING MECHANISM

- As shown in Figure 2.54, the electrically driven pump supplies the fluid under pressure to the operating cylinder through the solenoid operated valve.
- The piston is connected to the machine table.
- At the end of the forward stroke, the direction control valve reverses the direction of the flow through limit switches set at the stroke limits and the table moves backward.

RECIPROCATING MECHANISMS:

HYDRAULIC RECIPROCATING MECHANISM




FIGURE 2.54 Reciprocating mechanism (a) and velocity diagram (b) of hydraulic shaper.

MATERIAL SELECTION AND HEAT TREATMENT

OF MACHINE TOOL COMPONENTS

- The operating characteristics of a machine tool component depend on the proper choice of the material of each component.
- The most extensively used materials in machine tool components include CI and steels.

MATERIAL SELECTION AND HEAT TREATMENT

OF MACHINE TOOL COMPONENTS: CAST IRON

- In the majority of cases, machine tool beds and frames are made of gray CI (see Table 2.9) because of its good damping characteristics.
- If the guideways are cast as an integral part of the bed, frame, column, and so on, the high wear resistance grade CI (GG22 or A48-30B) with pearlitic matrix is recommended for medium-size machine tool beds and frames for a wall thickness of 10–30 mm and the grade GG26 or A48-40B for a wall thickness of 20–60 mm.
- High-strength, wear-resistant special gray CI of the grade (GG30 or A48-50B) with a pearlitic structure can be used for heavy machine tool beds with a wall thickness of more than 20 mm.

MATERIAL SELECTION AND HEAT TREATMENT OF MACHINE TOOL COMPONENTS: CAST IRON

TABLE 2.9
Grades of Gray CI According to DIN 1691, American Iron and Steel Institute (AISI),
Society of Automotive Engineers/American Society for Testing and Materials (SAE/ASTM)

DIN 1691	AISI, SAE/ASTM	C (%)	Brinell Hardness Number (BHN) (kg/mm ²)	Applications	Approximate Composition (%)
GG 12	A48-20B	3.5	160	No acceptance test for parts of no special requirements	C = 3.2–3.6, Si = 1.7–3, Mn = 0.5, P = 0.5, S = 0.12
GG 14	A48-26B	3.4	180		
GG 18	A48-30B	3.3	200		
GG 22	A48-30B	3.3	210	Machine parts and frames to withstand high stresses	
GG 26	A48-40B	3.2	230		
GG 30	A48-50B	2.8	240	Machine parts and frames of special quality	C = 2.8–3.0, Si = 1.5–1.7, Mn = 0.8–1.8, P = 0.3, S = 0.12

MATERIAL SELECTION AND HEAT TREATMENT OF MACHINE TOOL COMPONENTS: CAST IRON

- Due to the drawbacks associated with the manufacture of beds and frames by casting, beds and frames are made by welding rolled steel sheets.
- The elastic limit and the mechanical properties of such steel are higher than those of CI.
- Therefore, much less material (50–75%) is required for welded steel structures or beds than CI ones, to be subjected to the same forces and torques, if the rigidity and stiffness of the two structures are made equal.
- CI beds are more often used in large-lot production, while welded steel beds and frames are preferable in job or small-lot production.

MATERIAL SELECTION AND HEAT TREATMENT

OF MACHINE TOOL COMPONENTS: STEELS

- The majority of machine tool components, such as spindles, guides, shafts, springs, keys, forks, and levers, are generally made of steels.
- Since the Young's modulus of various types of steels cannot vary by more than $\pm 3\%$, the use of the alloy steels for machine tool components does not provide any advantages unless their application is dedicated by other requirements.
- Tables 2.10 and 2.11 show the different types of structural and alloy steels frequently used in machine tools.
- Structural steels are used when no special requirements are needed.
- Case hardening steels of carbon content $< 0.25\%$, phosphorous (P) or sulfur (S) should not exceed 0.40% are used when the surface hardness of the component should be very high while the core remains tough.

TABLE 2.10
Structural Steel According to DIN 17100 and AISI, SAE/ASTM

DIN 17100	AISI, SAE/ASTM	C (%)	Mechanical Properties			Hardening Temperature (°C)	Properties	Applications
			σ_u (kg/mm ²)	σ_e (kg/mm ²)	δ_5 (%)			
St 34	—	0.17	34–42	18	30	920	Case hardenable and weldable	Case hardened parts
St 37	—	0.20	37–45	—	25	920	Low grade, low weldability T ⁺ or M ⁺	General machine constructions
St 42	—	0.25	42–50	23	25	880–900	Case hardenable, hard core, machinable, not weldable	Machine elements and shafts withstanding variable loads
St 50	A570Cr50	0.35	50–60	27	22	820–850	Not case hardenable, not weldable, may be hardened, machinable	Machine elements and shafts withstanding heavy loads, not hardened gears
St 52	—	0.17	52–64	35	22	920	High strength, weldable	Welded steel construction in bridges and automobiles
St 60	—	0.45	60–70	30	17	800–820	Can be hardened and toughened	Same applications like St 50 but for higher loads, keys, gears, worms
St 70	—	0.60	70–85	35	12	780–800	Can be hardened and toughened	For parts in which wear resistance is recommended

Note: T, Thomas; M, Martin.

TABLE 2.11
Case Hardened Steels According to DIN 17210 and AISI, SAE/ASTM

DIN 17210	Quenching	AISI, SAE/ ASTM	Composition (%)				Mechanical Properties			Applications
			C	Mn	Cr	Ni	σ_u (kg/mm)	σ_e (kg/mm ²)	δ_5 (%)	
C 10	Water	1010	0.06–0.12	0.25–0.5	—	—	50	29	—	Typewriter parts
C 15		1015	0.12–0.18	0.25–0.5	—	—	55	35	—	Levers, bolts, sleeves
CK 10*		1010	0.06–0.12	0.25–0.5	—	—	50	30	20	Levers, bolts, pins of
CK 15*		1015	0.12–0.18	0.25–0.5	—	—	55–60	35	15	good surface finish
15Cr3		—	0.12–0.18	0.4–0.6	0.5–0.8	—	70–90	49	12	Spindles, cam shafts, piston pins, bolts, measuring tools
16MnCr3	Oil	5115	0.14–0.19	1–1.3	0.8–1.1	—	85–110	60	20–10	Pinions, automotive shafts, machine shafts
15CrNi6		—	0.12–0.17	0.4–0.6	1.4–1.7	1.4–1.7	95–120	70–90	15–6	Highly stressed small gears
20MnCr5		5120	0.17–0.22	1.1–1.4	1.0–1.3	—	110–145	75	12–7	Medium-size gears, automotive shafts, machine shafts
18CrNi8		—	0.15–0.22	0.4–0.6	1.8–2.1	1.8–2.1	120–145	90–110	14–7	Highly stressed gears, shafts, spindles, differential gears
41Cr4	Cy	5140	0.38–0.40	0.5–0.8	0.9–1.2	—	160–190	130–140	12–7	Cyanided gears

Note: CK 10* and CK 15* are carbon steels of quality better than C10 and C15 due to smaller contents of S and P; Cy, cyaniding.

MATERIAL SELECTION AND HEAT TREATMENT

OF MACHINE TOOL COMPONENTS: STEELS

- Typical applications of case-hardening steels are in gears, shafts, and spindles.
- Tempered steels, shown in Table 2.12, contain higher carbon content than case-hardened steels.
- They are used when high strength and toughness are required.
- Nonalloy tempered steels are used for machine components that are not heavily loaded.

MATERIAL SELECTION AND HEAT TREATMENT

OF MACHINE TOOL COMPONENTS: STEELS

- For components that are heavily loaded, such as gears, spindles, and shafts, the alloy type is recommended.
- Nitriding steels (see Table 2.13) contain aluminum as the main alloying element.
- After nitriding, the components possess an extraordinary surface hardness and therefore are used for machine parts subjected to wear such as spindles, guideways, and gears.
- The main advantage of the nitriding steel is minimum distortion after nitriding.

MATERIAL SELECTION AND HEAT TREATMENT

OF MACHINE TOOL COMPONENTS: STEELS

TABLE 2.12
Tempered Steels According to DIN 17100, AISI, SAE/ASTM

DIN 17100	AISI, SAE/ASTM	Composition (%)						Mechanical Properties			
		C	Si	Mn	Cr	Mo	Others	BHN	σ_u (kg/mm ²)	σ_s (kg/mm ²)	δ_5 (%)
C22	1020	0.18-0.25	0.15-0.36	0.3-0.6	—	—	—	155	50-60	30	22
C35	1035	0.32-0.40	0.15-0.36	0.4-0.7	—	—	—	172	60-72	37	18
C45	1045	0.42-0.50	0.15-0.36	0.5-0.8	—	—	—	206	65-80	40	16
C60	1060	0.57-0.65	0.15-0.36	0.5-0.8	—	—	—	243	75-90	40	14
CK22	1020-1023	0.18-0.25	0.15-0.36	0.3-0.6	—	—	—	155	50-60	30	22
CK35	1035	0.32-0.40	0.15-0.36	0.4-0.7	—	—	—	172	60-72	37	18
CK45	1045	0.42-0.50	0.15-0.36	0.5-0.8	—	—	—	206	65-80	49	16
CK60	1055	0.57-0.65	0.15-0.36	0.5-0.8	—	—	—	243	75-90	40	14
40Mn4	1039	0.36-0.44	0.25-0.50	0.8-1.1	—	—	—	217	80-95	55	14
30Mn5	1330	0.27-0.34	0.15-0.35	1.2-1.5	—	—	—	217	88-95	55	14
37MnSi5	—	0.38-0.41	1.1-1.4	1.1-1.4	—	—	—	217	90-105	56	12
42MnV7	—	0.38-0.45	0.15-0.35	1.6-1.9	—	—	0.07-0.12 V	217	100-120	80	11
34Cr4	—	0.30-0.37	0.15-0.55	0.5-0.8	0.9-1.2	—	—	217	90-105	65	12
41Cr4, 42Cr4	5140	0.38-0.44	0.15-0.55	0.5-0.8	0.9-1.2	—	—	217	90-105	65	12
25CrMo4	4130	0.22-0.29	0.15-0.55	0.5-0.8	0.9-1.2	—	—	217	80-95	55	14
34CrMo4	4135-4137	0.30-0.37	0.15-0.55	0.5-0.8	0.5-0.15	—	—	217	90-105	65	12
42CrMo4	4140-4142	0.38-0.45	0.15-0.55	0.5-0.8	0.9-1.2	—	—	217	100-120	80	11
50CrMo4	4150	0.46-0.54	0.15-0.55	0.5-0.8	0.9-1.2	0.15-0.25	—	235	110-130	90	10
30CrMoV9	—	0.26-0.34	0.15-0.55	0.4-0.7	2.3-2.7	—	0.1-0.2 V	248	125-145	105	9
36CrNiMo4	9840	0.32-0.40	0.15-0.55	0.5-0.8	0.9-1.2	—	0.9-1.2 Ni	217	100-120	80	11
34CrNiMo6	4340	0.30-0.38	0.15-0.55	0.4-0.7	1.4-1.7	—	1.4-1.7 Ni	235	110-130	90	10
30CrNiMo8	—	0.26-0.34	0.15-0.55	0.3-0.6	1.8-2.1	—	1.8-2.1 Ni	248	125-145	105	9
27NiCrV4	—	0.24-0.30	0.15-0.55	1.0-1.3	0.6-0.9	—	0.07-0.12 V	217	80-95	55	14
36Cr6	—	0.32-0.40	0.15-0.55	0.3-0.6	1.4-1.7	—	—	217	100-105	65	12
42CrV6	—	0.38-0.46	0.15-0.55	0.5-0.8	1.4-1.7	—	0.07-0.12 V	217	100-120	80	11
50CrV4	6150	0.47-0.56	0.15-0.55	0.8-1.1	0.9-1.12	—	0.07-0.12 V	235	110-130	90	10

MATERIAL SELECTION AND HEAT TREATMENT OF MACHINE TOOL COMPONENTS: STEELS

TABLE 2.13
Nitriding Steels

Not Specified in DIN	AISI, SAE/ASTM	Composition (%)					Mechanical Properties			Applications
		C	Cr	Al	Mn	Others	σ_u (kg/mm ²)	σ_e (kg/mm ²)	δ_5 (%)	
27CrAl6	—	0.27	1.5	1.1	0.6	—	85–80	45	16	Valve stems
34CrAl6	A355Cl.D	0.34	1.5	1.1	0.6	—	80–100	60	12	Shafts, measuring instruments
32AlCrMo4	—	0.32	1.1	1.1	0.6	0.2 Mo	80–95	60	12	Steam machinery shafts
32AlNi7	—	0.33	0.7	1.7	0.5	1.0 Ni	88–100	60	14	Piston rods, shafts
31CrMoV9	—	0.31	2.3	—	0.6	0.15Mo/0.1Ni	90–115	75	12	Cam- and crankshaft
30CrAlNi7	—	0.30	0.3	0.9	0.5	0.5 Ni	65–80	45	14	Spindles and shafts

TESTING OF MACHINE TOOLS

- After manufacture or repair of any machine tool, a machine tool test (usually called an acceptance test) should be performed according to the approved general specification.
- Such tests are essential because the accuracy and the surface quality of parts produced depend on the performance of the machine tool used.
- Testing machine tools has the following general advantages:
 1. Determines the precision class and the accuracy capabilities of the machine tool
 2. Prepares plans for preventive maintenance
 3. Determines the actual condition and hence the expected life of the machine tool

TESTING OF MACHINE TOOLS

- Machine tool tests are classified into two categories:
 1. geometrical alignment tests
 2. Performance tests.
- Geometrical tests cover the manufactured accuracy of machine tools.
- These tests are carried out to determine the various relationships between the various machine tool elements when idle and unloaded (static test).
- They include checking parallelism of the spindle and a lathe bed, squareness of the table movement to the milling machine spindle, straightness of guideways, and so on.
- Static tests are inadequate to judge the machine tool performance, because they do not reveal the machine tool rigidity or the accuracy of machining.

TESTING OF MACHINE TOOLS

- The normal procedure for acceptance tests is made through the following steps:
 1. Checking the principal horizontal and vertical planes and axes using a spirit level
 2. Checking the guiding and bearing surfaces for parallelism, flatness, and straightness, using dial gauge, test mandrel, straight edge, and squares
 3. Checking the various movements in different directions using dial gauges, mandrels, straight edges, and squares
 4. Testing the spindle concentricity, axial slip, and accuracy of axis
 5. Conducting working tests to check whether the accuracy of machined parts are within the specified limits
 6. Preparing acceptance charts for the machine tool that specify the type of test and the range of allowable limits of deformation, deflection, error in squareness, flatness eccentricity, parallelism, and amplitude of vibrations

TESTING OF MACHINE TOOLS

- In contrast, dynamic tests are used to check the working accuracy of machine tools through the
- following steps:
 1. Performing an idle run test and operation check mechanisms
 2. Checking for geometrical accuracy and surface roughness of the machined parts
 3. Performing rigidity and vibration tests
- Standards for testing machine tools are covered by Schlesinger (1961).


MAINTENANCE OF MACHINE TOOLS

- Machine tools cannot produce accurate parts throughout their working life if there is excessive wear in their moving parts.
- Machine tool maintenance delays the possible deterioration in machine tools and avoids the machine stoppage time that leads to lower productivity and higher production cost.
- Maintenance is classified under the following schemes.
 1. Preventive Maintenance
 2. Corrective Maintenance
 3. Reconditioning

MAINTENANCE OF MACHINE TOOLS:

PREVENTIVE MAINTENANCE

- Preventative maintenance is mainly carried out to reduce wear and prevent disruption of the production program.
- Lubrication of all the moving parts that are subjected to sliding or rolling friction is essential.
- A regular planned preventive maintenance consists of minor and medium repairs as well as major overhaul.
- The features of a well-conceived preventive maintenance scheme include
 1. adequate records covering the volume of work,
 2. inspection frequency schedule,
 3. identification of all items to be included in the maintenance program,
 4. well-qualified personnel.
- Preventive maintenance of machine tools ensures reliability, safety, and the availability of the right machine at the right time.



MAINTENANCE OF MACHINE TOOLS:

CORRECTIVE MAINTENANCE

- When a machine tool is in use, it should be regularly checked to determine whether wear has reached the level when corrective maintenance should be carried out to avoid machine tool failure.
- A record of all previous repairs shows those elements of the machine tool that need frequent inspection.
- Additionally, such records are used for decisions regarding the need for machine tool reconditioning and replacement.

MAINTENANCE OF MACHINE TOOLS:

RECONDITIONING

- The need for machine tool recondition is determined by the frequency of the corrective maintenance repairs.
- Every machine tool component has a certain life span beyond which it becomes unserviceable despite the best preventive maintenance.
- A major overhaul or reconditioning is required.
- Inspection reports of the machine indicate the components to be replaced, labor time, and the cost estimate.
- As a general rule, it is undesirable to recondition the machine if the cost exceeds 50% of buying new equipment.

REVIEW QUESTIONS

1. State the main requirements of a machine tool.
2. Give examples for open and closed machine tool structures.
3. Explain why closed box elements are best suited for machine tool structures.
4. Sketch the different types of ribbing systems used in machine tool frames.
5. Explain what is meant by light- and heavyweight construction in machine tools.
6. Sketch the different types of machine tool guideways.
7. Show how wear is compensated for in machine tool guideways.
8. Differentiate between cast and welded structures.

REVIEW QUESTIONS

9. Distinguish among the kinematic, structural, and speed diagrams of gearboxes.
10. Show an example of externally pressurized and rolling friction guideways.
11. Show the different schemes of spindle mounting in machine tools.
12. What are the main applications of pick-off gears, feed gearboxes with a sliding gear, and Norton gearboxes?
13. Compare between toroidal and disk-type stepless speed mechanisms.
14. Give examples for speed-reversing mechanisms in machine tools.
15. Derive the relationship between the cutting and the reverse speeds of the quick-return mechanism used in the mechanical shaper.
16. State the main objectives behind machine tool testing.
17. Compare between corrective and preventive maintenance of machine tools.

Lecture 3-1: General-Purpose Machine Tools: Lathe Machines and Operations

Dr. Parviz Kahhal

INTRODUCTION

- Machine tools are factory equipment used for producing machines, instruments, tools, and all kinds of spare parts.
- Therefore, the size of a country's stock of machine tools, and their technical quality and condition, characterize its industrial and technical potential fairly well.
- Metal cutting machine tools are mainly grouped into the following categories:
- General-purpose machine tools.
 - These are multipurpose machines used for a wide range of work.
- Special-purpose machine tools.
 - These are machines used for making one type of part of a special configuration, such as screw thread and gear cutting machines.
- Capstan, turret, and automated lathes.
- Numerical and computer numerical controlled machine tools.

INTRODUCTION

- In this chapter, the general-purpose machine tools are characterized and dealt with in brief.
- This group of machine tools comprises:
 - lathes,
 - drilling machines,
 - milling machines,
 - shapers,
 - planers,
 - slotters,
 - boring machines,
 - jig boring machines,
 - broaching machines,
 - microfinishing machines.


LATHE MACHINES AND OPERATIONS

- Lathes are generally considered to be the oldest machine tools still used in industry.
- About one third of the machine tools operating in engineering plants are lathe machines.
- Lathes are employed for turning external cylindrical, tapered, and contour surfaces; boring cylindrical and tapered holes, machining face surfaces, cutting external and internal threads, knurling, centering, drilling, counterboring, countersinking, spot facing and reaming of holes, cutting off, and other operations.
- Lathes are used in both job and mass production.

LATHE MACHINES AND OPERATIONS: TURNING OPERATIONS

- In operations performed on lathes (turning operations), the primary cutting motion v (rotary) is imparted to the WP, and the feed motion f (in most cases straight along the axis of the WP) is imparted to a single-point tool.
- The tool feed rate f is usually very much smaller than the surface speed v of the WP.

LATHE MACHINES AND OPERATIONS: TURNING OPERATIONS



Basic machining parameters in turning.

LATHE MACHINES AND OPERATIONS: TURNING OPERATIONS

- Basic machining parameters in turning include:

1. Cutting speed v

$$v = \frac{\pi D n}{1000} \text{ m/min}$$

where

D = initial diameter of the WP (mm)

n = rotational speed of the WP (rpm)

LATHE MACHINES AND OPERATIONS: TURNING OPERATIONS

2. Rotational speed n

$$n = \frac{1000v}{\pi D} \text{ rpm}$$

3. Feed rate f , which is the movement of the tool cutting edge in millimeters per revolution of the WP (mm/rev).

4. Depth of cut t , which is measured in a direction perpendicular to the WP axis, for one turning pass.

$$t = \frac{D - d}{2} \text{ mm}$$

LATHE MACHINES AND OPERATIONS: TURNING OPERATIONS

5. Undeformed chip cross-section area A_c

$$A_c = f \cdot t = h \cdot b \text{ mm}^2$$

where

h = chip thickness in millimeters ($h = f \sin \chi$ mm)

b = contact length in millimeters

χ = cutting edge angle (setting angle)


LATHE MACHINES AND OPERATIONS: TURNING OPERATIONS

TABLE 3.1
Lathe Operations and Relevant Tools


Lathe Operation and Relevant Tool

1. Cylindrical turning with a straight-shank turning tool
2. Taper turning with a straight-shank turning tool
3. Facing of a WP with:
 - a. Facing tool while the WP is clamped by a half center
 - b. Facing tool while the WP is mounted in a chuck


Sketch and Directions of Cutting Movements




4. Finish turning with:
 a. Broad-nose finishing tool
 b. Straight finishing tool with a nose radius



5. Necking or recessing with:
 a. Recessing tool
 b. Wide recessing tool
 c. Wide recessing using narrow recessing tool




6. Parting off with parting-off tool




LATHE MACHINES AND OPERATIONS: TURNING OPERATIONS

7. Boring of cylindrical hole with:
 a. Bent rough-boring tool
 b. Bent finish-boring tool




8. Threading with:
 a. External threading tool
 b. Internal threading tool



LATHE MACHINES AND OPERATIONS: TURNING OPERATIONS


9. Drilling and core drilling with a twist drill:

- a. Originating with a twist drill
- b. Enlarging with a twist drill
- c. Enlarging with a core drill



10. Forming with:

- a. Straight forming tool
- b. Flat dovetailed tool
- c. Circular form tool



LATHE MACHINES AND OPERATIONS: METAL CUTTING LATHES

Every engine lathe provides a means for traversing the cutting tool along the axis of revolution of the WP and at right angles to it.

Beyond this similarity, the lathe may embody other characteristics common to several classifications according to fields of application that ranges from manual to full automatic machining.

Metal cutting lathes may differ in size and construction.

Among these are the general-purpose machines that include universal engine lathes, plain turning lathes, facing lathes, and vertical turning and boring mills.

METAL CUTTING LATHES:

Universal Engine Lathes

- Universal engine lathes are widely employed in job and lot production, as well as for repair work.
- Parts of very versatile forms may be machined by this lathe.
- Its size varies from small bench lathes to heavy-duty lathes for machining parts weighing many tons.
- Figure 3.2 illustrates a typical universal engine lathe.

METAL CUTTING LATHES:

Universal Engine Lathes




FIGURE 3.2 Typical engine lathe.

METAL CUTTING LATHES:

Universal Engine Lathes

- The bed (2) carries the headstock (1), which contains the speed gearbox.
- The bed also mounts the tailstock (6) whose spindle usually carries the dead center.
- The work may be held between centers, clamped in a chuck, or held in a fixture mounted on a faceplate.
- If a long shaft (5) is to be machined, it will be insufficient to clamp one end in a chuck; therefore, it is necessary to support the other end by the tailstock center.
- In many cases when the length of the shaft exceeds 10 times its diameter ($l > 10 D$), a steady rest or follower rest is used to support these long shafts.

METAL CUTTING LATHES:

Universal Engine Lathes

- Single-point tools are clamped in a square turret (4) mounted on the carriage (3).
- Tools such as drills, core drills, and reamers are inserted in the tailstock spindle after removing the center.
- The carriage (3), to which the apron (10) is secured, may traverse along the guideways either manually or powered.
- The cross slide can also be either manually or power traversed in the cross direction.
- Surfaces of revolution are turned by longitudinal traverse of the carriage.
- The cross slide feeds the tool in the cross direction to perform facing, recessing, forming, and knurling operations.
- Power traverse of the carriage or cross slide is obtained through the feed mechanism.

METAL CUTTING LATHES:

Universal Engine Lathes

- Rotation is transmitted from the spindle through change gears and the quick change feed gearbox (11) to either the lead screw (8) or feed rod (9).
- From either of these, motion is transmitted to the carriage. Powered motion of the lead screw is used only for cutting threads using a threading tool.
- In all other cases, the carriage is traversed by hand or powered from the feed rod. Carriage feed is obtained by a pinion and rack (7) fastened to the bed.
- The pinion may be actuated manually or powered from the feed rod. The cross slide is powered by the feed rod through a gearing system in the apron (10).
- During thread cutting, the half nuts (9) are closed by the lever (10) over the lead screw (1).

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 19

METAL CUTTING LATHES:

Universal Engine Lathes




FIGURE 3.3 Lathe apron mechanism.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 20

METAL CUTTING LATHES:

Universal Engine Lathes

- **Specifications of an Engine Lathe**
- Figure 3.4 shows the main dimensions that indicate the capacity of an engine lathe. These are:
- Maximum diameter D of work accommodated over the bed (swing over bed). According to most of national standards, D varies from 100 to 6300 mm, arranged in geometric progression $\phi = 1.26$.
- Maximum diameter D_1 of work accommodated over the carriage.
- Distance between centers, which determines the maximum work length. It is measured with the tailstock shifted to its extreme right-hand position without overhanging.
- Maximum bore diameter of spindle, which determines the bar capacity (maximum bar stock).

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 21

METAL CUTTING LATHES:

Universal Engine Lathes




FIGURE 3.4 Main dimensions of an engine lathe.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 22

METAL CUTTING LATHES:

Universal Engine Lathes


- In addition to these dimensions, other important specifications are:
- Number of spindle speeds and speed range
- Number of feeds and feed range
- Motor power and speed
- Overall dimensions and net weight

METAL CUTTING LATHES:

Universal Engine Lathes

- *Setting Up the Engine Lathe for Taper Turning*
- Tapered surfaces are turned by employing one of the following methods (Figure 3.5):
 - a) By swiveling the compound rest to the required angle α . Before performing the operation, the compound rest is to be clamped in this position. The tool is fed manually by rotating handle (1).
- This method is used for turning short internal and external tapers with large taper angles, while the work is commonly held in a chuck and a straight turning tool is used (Figure 3.5a).

METAL CUTTING LATHES: Universal Engine Lathes




● Lecture 3: General-Purpose Machine tools

Dr. Parviz Kahhal ● 25

METAL CUTTING LATHES: Universal Engine Lathes

- b) By using a straight-edge broad-nose tool. The tool of width that exceeds the taper being turned is cross-fed. The work is held in a chuck or clamped on a faceplate (Figure 3.5b).



● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 26


METAL CUTTING LATHES:

Universal Engine Lathes

- c) By setting over the tailstock.
- The angle of taper α should not exceed 8° . Since the turned surface is parallel to the spindle axis, the powered feed of the carriage can be used while the work is to be mounted between centers as shown in Figure 3.5c.
 - Before turning cylindrical surfaces, it is a good practice to check whether the tailstock is not previously set over for taper turning; otherwise, tapered surfaces are produced.

METAL CUTTING LATHES:


Universal Engine Lathes



METAL CUTTING LATHES:

Universal Engine Lathes

- d) By using a taper-turning attachment. This is best suited for long tapered work. The cross slide (1) is disengaged from the cross feed screw and is linked through the tie (2) to the slide (3) (Figure 3.5d).



● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 29

METAL CUTTING LATHES:

Universal Engine Lathes


- *Setting Up the Engine Lathe for Turning Contoured Surfaces with a Tracer Device*
- Longitudinal contoured surfaces are produced using a tracer device similar to the taper-turning attachment, except that the template of the required profile is substituted by the guide bar.
- Disadvantages of such mechanical duplicating are the difficulties in making a template sufficiently accurate and strong enough to withstand the cutting force and the rapid wear of such templates.
- A mechanical tracer for turning spherical surfaces, shown in Figure 3.6, operates by similar principles.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 30

METAL CUTTING LATHES:

Universal Engine Lathes



Turning of a spherical surface.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 31

METAL CUTTING LATHES:

Universal Engine Lathes

- Accordingly, the template (1) is clamped in the tailstock spindle and a roller (2) is clamped in the square turret opposite the tool (3) and in contact with the template.
- If the cross feed is transmitted to the cross slide, the profile of the template will be produced on the WP.
- When much contour turning work is to be done with longitudinal feeds, a hydraulic tracer slide is often installed on engine lathe where the stylus sliding on the template does not carry the cutting force.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 32

METAL CUTTING LATHES:

Universal Engine Lathes

- *Setting Up the Engine Lathe for Cutting Screw Threads*
- In some cases when the machine has not a quick-change gearbox, or when the thread pitch to be cut is nonstandard, change gears must be used and setup on the quadrant as shown in Figure 3.7.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 33

METAL CUTTING LATHES:

Universal Engine Lathes




FIGURE 3.7 Setting up the engine lathe for thread cutting.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 34

METAL CUTTING LATHES:

Universal Engine Lathes

- Because one revolution of the spindle provides the pitch t_{th} of the screw thread to be produced, the kinematic linkage is given by the following equation:

$$t_{th} = t_{ls} \cdot i_{cg}$$

$$i_{cg} = \frac{t_{th}}{t_{ls}} = \frac{a}{b} \times \frac{c}{d}$$


where

- t_{ls} = pitch of the lead screw of the lathe
- i_{cg} = gearing ratio of the quadrant
- a, b, c, d = number of teeth of change gears

METAL CUTTING LATHES:

Universal Engine Lathes


- *Holding the Work on Engine Lathe*
 - WP fixation on an engine lathe depends mainly upon the geometrical features of the WP and the precision required. The WP can be held between centers, on a mandrel, in a chuck, or on a faceplate:
1. **Holding the WP between centers**
 - A dog plate (1) and a lathe dog (2) are used (Figure 3.8a).
 - It is an accurate method for clamping a long WP.



METAL CUTTING LATHES:

Universal Engine Lathes

- The tailstock center may be a dead center (Figure 3.8b), or a live center (Figure 3.8c), when the work is rotating at high speed. In such a case, rests are used to support long WPs to prevent their deflection under the action of the cutting forces.




● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 37

METAL CUTTING LATHES:

Universal Engine Lathes

- The steady rest (Figure 3.9a) is mounted on the guideways of the bed while the follower rest (Figure 3.9b) is mounted on the saddle of the carriage.



● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 38

METAL CUTTING LATHES:

Universal Engine Lathes

2. Clamping hollow WPs on mandrels.

- Mandrels are used to hold WPs with previously machined holes. The WP to be machined (2) is tightly fitted on a conical mandrel, tapered at 0.001, and provided with center holes to be clamped between centers using a dog plate and a lathe dog (Figure 3.10a).
- The expanding mandrel (Figure 3.10b) consists of a conical rod (1), a split sleeve (2), and nuts (3 and 4).
- The work is held by expansion of a sleeve (2), as the latter is displaced along the conical rod (1) by nut (3).
- Nut (4) removes the work from the mandrel.
- There is a flat (5) on the left of the conical rod used for the setscrew of the driving lathe dog.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 39

METAL CUTTING LATHES:

Universal Engine Lathes




FIGURE 3.10 Mounting WPs on a mandrel.

• Lecture 3: General-Purpose Machine Tools


Dr. Parviz Kahhal • 40

METAL CUTTING LATHES:

Universal Engine Lathes

3. Clamping the WP in a chuck.

- The most commonly employed method of holding short work is to clamp it in a chuck (Figure 3.11 a).




• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 41

METAL CUTTING LATHES:

Universal Engine Lathes

- If the work length is considerably large relative to its diameter, supporting the free end with the tailstock dead or live center (Figure 3.11 b) is also used.




• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 42

METAL CUTTING LATHES:

Universal Engine Lathes

- Chucks may be universal (self-centering) of three jaws, which are expanded and drawn simultaneously (Figure 3.11c).




• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 43

METAL CUTTING LATHES:


Universal Engine Lathes

- they may be independent of four jaws (Figure 3.11d).



• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 44



METAL CUTTING LATHES:

Universal Engine Lathes

- The three-jaw chucks are used to clamp circular and hexagonal rods, whereas the independent four-jaw chucks are especially useful in clamping irregular and nonsymmetrical WPs.
- Air-operated (pneumatic) chucks are commonly used in batch or mass production by increasing the degree of automation (Figure 3.12).
- The piston (1) is attached to a rod that moves it to the right or to the left depending on which chamber of the pneumatic cylinder is fed with compressed air.
- The end of the rod is connected to three levers (2), which expand jaws (3) in a radial direction to clamp or release the WP.

METAL CUTTING LATHES: Universal Engine Lathes




FIGURE 3.12 Pneumatic chuck.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 47

METAL CUTTING LATHES: Universal Engine Lathes

4. Clamping the WP on a faceplate.


- Large WPs cannot be clamped in a chuck and are, therefore, mounted either directly on a faceplate (Figure 3.13a), or mounted on a plate fixture (2) that is attached to faceplate (1) (Figure 3.13b).
- The work (3) and angle plate (2) must be counterbalanced by using the counterweight (4) mounted at the opposite position on the faceplate.
- The plate fixture has been proved to be highly efficient in machining asymmetrical work of complex and irregular shape.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 48

METAL CUTTING LATHES:

Universal Engine Lathes



Mounting WPs on faceplates.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 49

Other Types of General-Purpose Metal Cutting Lathes

- These include plain turning lathes, facing lathes, and vertical turning and boring mills.
- Facing
- lathes, vertical turning and boring mills, and heavy-duty plain turning lathes are generally used for heavy work.
- They are characterized by low speeds, large feeds, and high cutting torques.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 50

Other Types of General-Purpose Metal

Cutting Lathes: Plain turning lathes

1. Plain turning lathes.

- Plain turning lathes differ from engine lathes in that they do not have a lead screw. They perform all types of lathe work except threading and chasing. The absence of the lead screw substantially simplifies the kinematic features and the construction of the feed gear trains.
- Their dimensional data are similar to those of engine lathes. Plain turning lathes are available in three different size ranges: small, medium, and heavy duty.
- Heavy-duty plain turning lathes have several common carriages that are powered either from a common feed rod, linked kinematically to the lathe spindle, or powered from a variable speed dc motor mounted on each carriage.
- The tailstock traverses along the guideway by a separate drive.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 51

Other Types of General-Purpose Metal Cutting Lathes: Facing lathes.

2. Facing lathes.

- These are used to machine work of large diameter and short length in single-piece production and for repair jobs.
- These machines are generally used for turning external, internal, and taper surfaces, facing, boring, and so on.
- Facing lathes have relatively small length and large diameter of faceplates (up to 4 m).
- Sometimes, they are equipped with a tailstock.
- Its construction differs, to some extent, from the center lathe.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 52

Other Types of General-Purpose Metal Cutting Lathes: Facing lathes.

- It consists of the base plate (1), headstock (4) with faceplate (5), bed (2), carriage (3), and tailstock (6) (Figure 3.14).
- The work is clamped on the faceplate using jaws, or clamps, and T-slot bolts.
- It may be additionally supported by the tailstock center.
- The feed gear train is powered from a separate motor to provide the longitudinal and transverse feeds.
- Facing lathes have been almost superseded by vertical turning and boring mills; however, because of their simple construction and low cost, they are still employed.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 53




FIGURE 3.14 Facing lathe.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 54

Other Types of General-Purpose Metal Cutting Lathes:

Vertical turning and boring mills.

- These machines are employed in machining heavy pieces of large diameters and relatively small lengths.
- They are used for turning and boring of cylindrical and tapered surfaces, facing, drilling, countersinking, counterboring, and reaming.
- In vertical turning and boring mills, the heavy work can be mounted on rotating tables more conveniently and safely as compared to facing lathes.
- The horizontal surface of the worktable excludes completely the overhanging load on the spindle of the facing lathes.
- This facilitates the application of high-velocity machining and, at the same time, enables high accuracy to be attained.
- These small machines are called vertical turret lathes. As their name implies, they are equipped with turret heads, which increase their productivity.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 55

Lecture 3-2: General-Purpose Machine Tools: Drilling Machines and Operations

Dr. Parviz Kahhal

Drilling and Drilling Allied Operations

- **Drilling Operation**
- Drilling is a process used extensively by which through or blind holes are originated or enlarged in a WP.
- This process involves feeding a rotating cutting tool (drill) along its axis of rotation into a stationary WP (Figure 3.15).
- The axial feed rate f is usually very small when compared to the peripheral speed v .
- Drilling is considered a roughing operation and, therefore, the accuracy and surface finish in drilling are generally not of much concern.
- If high accuracy and good finish are required, drilling must be followed by some other operation such as reaming, boring, or grinding.

Drilling and Drilling Allied Operations




FIGURE 3.15 Drilling operation.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 3

Drilling and Drilling Allied Operations

- The most commonly employed drilling tool is the twist drill, which is available in diameters ranging from 0.25 to 80 mm.
- A standard twist drill (Figure 3.16) is characterized by a geometry in which the normal rake and the velocity of the cutting edge are a function of their distance from the center of the drill.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 4

Drilling and Drilling Allied Operations




FIGURE 3.16 Terminology of a standard point twist drill.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 5


Drilling and Drilling Allied Operations

- Referring to the terminology of twist drill shown in Figure 3.17, the helix angle of the twist drill is the equivalent of the rake angle of other cutting tools.
- The standard helix is 30° , which, together with a point angle of 118° , is suitable for drilling steel and CI (Figure 3.17a).
- Drills with a helix angle of 20° , known as slow-helix drills, are available with a point of 118° for cutting brass and bronze (Figure 3.17b), and with a point of 90° for cutting plastics. Quick helix drills, with a helix angle of 40° and a point of 100° , are suitable for drilling softer materials such as aluminum alloys and copper (Figure 3.17c). Figure 3.18 visualizes the basic machining parameters in drilling and enlarging holes.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 6

Drilling and Drilling Allied Operations




Helix drills of different helix angles: (a) Standard, (b) slow, (c) quick.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 7

Drilling and Drilling Allied Operations



Basic machining parameters in drilling.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 8

Drilling and Drilling Allied Operations

- **Drilling Allied Operations**
- Drilling allied or alternative operations such as core drilling, center drilling, counterboring, countersinking, spot facing, reaming, tapping, and other operations can also be performed on drilling machines as shown in Figure 3.19.
- Accordingly, the main and feed motion are the same as in drilling; that is, the drill rotates while it is fed into the stationary WP.
- In these processes, the tool shape and geometry depend upon the machining process to be performed.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 9

Drilling and Drilling Allied Operations




FIGURE 3.19 Drilling and drilling allied operations.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 10

Drilling and Drilling Allied Operations

- The same operations can be accomplished in some other machine by holding the tool stationary and rotating the work. The most general example is performing these processes on a center lathe, in which the tool (drill, counterbore, reamer, tap, and so on) is held in the tailstock and the work is held and rotated by a chuck (Figure 3.20).

Drilling and Drilling Allied Operations





FIGURE 3.20 Drilling and drilling allied operations as performed on an engine lathe: (a) Drilling and (b) Countersinking.

Drilling and Drilling Allied Operations



Counterboring, countersinking, and spot facing operations.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 13

GENERAL-PURPOSE DRILLING MACHINES

- The general-purpose drilling machines are classified as
 1. Bench-type sensitive drill presses
 2. Upright drill presses
 3. Radial drills
 4. Multispindle drilling machines
 5. Horizontal drilling machines for drilling deep holes
- The most widely used in the general engineering industries are the upright drill presses and radial drills.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 14

GENERAL-PURPOSE DRILLING MACHINES

- **Bench-Type Sensitive Drill Presses**
- These drill presses are used for machining small diameter holes of 0.25–12 mm diameter.
- Manual feeding characterizes this machine and that is why they are called “sensitive.”
- High speeds are typical for bench-type sensitive drill presses.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 15

GENERAL-PURPOSE DRILLING MACHINES

- **Upright Drill Presses**
- These machines are used for machining holes up to 50 mm in diameter in relatively small-size work.
- It has a wide range of spindle speeds and feeds.
- Therefore, they are employed not only for drilling from solid material, but also for core drilling, reaming, and tapping operations.
- Figure 3.23 illustrates the gearing diagram of the machine.





FIGURE 3.22 Typical upright drill press.
Dr. Parviz Kahhal • 16

• Lecture 3: General-Purpose Machine Tools

GENERAL-PURPOSE DRILLING MACHINES



● Lecture 3: General-Purpose Machine Tools **FIGURE 3.23** Kinematic diagram of an upright drill press. Dr. Parviz Kahhal ● 17

GENERAL-PURPOSE DRILLING MACHINES

- Cutting movements.
- As shown in the gearing diagram (Figure 3.23), the kinematic chain equations for the maximum spindle speed and feed are given by

$$n_{\max} = 1420 \cdot \frac{27}{27} \cdot \frac{33}{33} \cdot \frac{52}{26} = 2840 \text{ rpm}$$

$$f_{\max} = 1 \cdot \frac{22}{42} \cdot \frac{24}{24} \cdot \frac{32}{21} \cdot \frac{17}{44} \cdot \frac{1}{60} \times \pi \times 2.5 \times 14 = 0.56 \text{ mm/rev}$$

GENERAL-PURPOSE DRILLING MACHINES

- **Auxiliary movements.**
- The drill head, housing the speed and feed gearboxes, moves along the machine column through the gear train: worm gearing 1/20-rack and pinion ($z = 14$, $m = 2$). The machine table can be moved vertically by hand through bevels 18/45 and an elevating screw driven by means of a handle (Figure 3.23).

GENERAL-PURPOSE DRILLING MACHINES

- **Radial Drilling Machines.**
- These machines are especially designed for drilling, counterboring, countersinking, reaming, and tapping holes in heavy and bulky WPs that are inconvenient or impossible to machine on the upright drilling machines. They are suitable for multitool machining in individual and batch production.


GENERAL-PURPOSE DRILLING MACHINES

- Radial drilling machines (Figure 3.24) differ from upright drill presses in that the spindle axis is made to coincide with the axis of the hole being machined by moving the spindle in a system of polar coordinate to the hole, while the work is stationary.
- This is achieved by:
 1. Swinging the radial arm (4) about the rigid column (2)
 2. Raising or lowering the radial arm on the column by the arm-elevating and -clamping mechanism (3) to accommodate the WP height
 3. Moving the spindle head (5) along the guideways of the radial arm (4)

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 21

GENERAL-PURPOSE DRILLING MACHINES



Typical radial drilling machine.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 22

GENERAL-PURPOSE DRILLING MACHINES

- Accordingly, the tool is located at any required point on the stationary WP, which is set either on detachable table (6) or directly on base (1).
- After the maneuvering tasks performed by the radial arm and spindle head, they are held in position using power-operated clamping devices.
- The spindle head gearing diagram of the radial drilling machine is very similar to that of the upright drill press.

GENERAL-PURPOSE DRILLING MACHINES

- **Multispindle Drilling Machines.**
- These are mainly used in lot production for machining WPs requiring simultaneous drilling, reaming, and tapping of a large number of holes in different planes of the WP.
- A single spindle drilling machine is not economical for such purposes, as not only a considerably large number of machines and operators are required but also the machining cycle is longer.

GENERAL-PURPOSE DRILLING MACHINES

- There are three types of multiplespindle drilling machines:
 - a. Gang multispindle drilling machines.
 - The spindles (2-6) are arranged in a row, and each spindle is driven by its own motor.
 - The gang machine is in fact several upright drilling machines having a common base and single worktable (Figure 3.25). They are used for consecutive machining of different holes in one WP, or for the machining of a single hole with different cutting tools.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 25

GENERAL-PURPOSE DRILLING MACHINES




FIGURE 3.25 Gang, multiple-spindle drilling machine.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 26

GENERAL-PURPOSE DRILLING MACHINES

b. Adjustable-center multispindle vertical drilling machines. These differ from gang-type machines in that they have a common drive for all working spindles.

The spindles are adjusted in the spindle head for drilling holes of varying diameters at random locations on the WP surface (Figure 3.26).




FIGURE 3.26 Multiple-spindle drilling machine.
Dr. Parviz Kahhal ● 27

● Lecture 3: General-Purpose Machine Tools

GENERAL-PURPOSE DRILLING MACHINES

c. Unit-type multispindle drilling machines.

These are widely used in mass production.

They are, as a rule, chiefly built of standard units. Such machines are designed for machining a definite component held in a jig and are frequently built into an automatic transfer machine (Figure 3.27).

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 28

GENERAL-PURPOSE DRILLING MACHINES




FIGURE 3.27 Unit-type multiple-spindle drilling machine.
● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 29

Lecture 3-3: General-Purpose Machine Tools: Milling Machines and Operations

Dr. Parviz Kahhal

MILLING OPERATIONS

- Milling is the removal of metal by feeding the work past a rotating multitoothed cutter. In this operation the material removal rate (MRR) is enhanced as the cutter rotates at a high cutting speed.
- The surface quality is also improved due to the multicutting edges of the milling cutter.
- The action of the milling cutter is totally different from that of a drill or a turning tool. In turning and drilling, the tools are kept continuously in contact with the material to be cut, whereas milling is an intermittent process, as each tooth produces a chip of variable thickness.
- Milling operations may be classified as peripheral (plain) milling or face (end) milling (Figure 3.38).

MILLING OPERATIONS




FIGURE 3.38 Plain and face milling cutters: (a) Plain milling and (b) face milling.

MILLING OPERATIONS

- **Up-Milling (Conventional Milling)**
- Up-milling is accomplished by rotating the cutter against the direction of the feed of the WP (Figure 3.39a).
- The tooth picks up from the material gradually; that is, the chip starts with no thickness and increases in size as the teeth progress through the cut.
- This means that the cycle of operation to remove the chip is first a sliding action at the beginning and then a crushing action takes place, which is followed by the actual cutting action.
- In some metals, up-milling leads to strain hardening of the machined surface, and also to chattering and excessive teeth blunting.

MILLING OPERATIONS




FIGURE 3.39 Up-milling and down-milling: (a) Up-milling (conventional cut) and (b) down-milling (climb cut).

MILLING OPERATIONS

- Advantages of up-milling include the following:
- It does not require a backlash eliminator.
- It is safer in operation (the cutter does not climb on the work).
- Loads on teeth are acting gradually.
- Built-up edge (BUE) fragments are absent from the machined surface.
- The milling cutter is not affected by the sandy or scaly surfaces of the work.


MILLING OPERATIONS

- **Down-Milling (Climb Milling).**
- Down-milling is accomplished by rotating the cutter in the direction of the work feed, as shown in Figure 3.39b.
- In climb milling, as implied by the name, the milling cutter attempts to climb the WP.
- Chips are cut to maximum thickness at initial engagement of cutter teeth with the work, and decrease to zero at the end of its engagement.
- The cutting forces in down milling are directed downward. Down-milling should not be attempted if machines do not have enough rigidity and are not provided with backlash eliminators (Figure 3.40).
- Under such circumstances, the cutter climbs up on the WP and the arbor and spindle may be damaged.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 7

MILLING OPERATIONS



Backlash eliminator in down-milling.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 8

MILLING OPERATIONS

- Advantages of down-milling include the following:
- Fixtures are simpler and less costly, as cutting forces are acting downward.
- Flat WPs or plates that cannot be firmly held can be machined by down-milling.
- Cutter with higher rake angles can be used, which decreases the power requirements.
- Tool blunting is less likely.
- Down-milling is characterized by fewer tendencies of chattering and vibration, which leads to improved surface finish.

MILLING OPERATIONS

- **Face Milling.**
- In face milling, the generated surface is at a right angle to the cutter axis.
- When using cutters of large diameters, it is a good practice to tilt the spindle head slightly at an angle of $1-3^\circ$ to provide some clearance, which leads to an improved surface finish and eliminate tool blunting (Figure 3.38b).
- Face milling is usually performed on vertical milling machines; for this reason, the process is called vertical milling, which is more productive than plain milling.


MILLING CUTTERS

- The milling cutters are selected for each specified machining duty.
- The milling cutter may be provided with a hole to be mounted on the arbor of the horizontal milling machines, or provided with a straight or tapered shank for mounting on the vertical or horizontal milling machine.

MILLING CUTTERS

1. Plain milling cutters are either straight or helical ones. Helical milling cutters are preferred for large cutting widths to provide smooth cutting and improved surface quality.


- Plain milling cutters are mainly used on horizontal milling machines.



MILLING CUTTERS

2. Face milling cutters are used for the production of horizontal (Figure 3.41b), vertical (Figure 3.41c), or inclined (Figure 3.41d) flat surfaces.

- They are used on vertical milling machines, planer type milling machines, and vertical milling machines with the spindle swiveled to the required angle α , respectively.




• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 13

MILLING CUTTERS

3. Side milling cutters are clamped on the arbor of the horizontal milling machine and are used for machining of the vertical surface of a shoulder (Figure 3.41e) or cutting a keyway (Figure 3.41f).



• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 14

MILLING CUTTERS

4. Interlocking (staggered) side mills (Figure 3.41g) mounted on the arbor of the horizontal milling machines are intended to cut wide keyways and cavities.




(g)

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 15

MILLING CUTTERS

5. Slitting saws (Figure 3.41h) are used on horizontal milling machines.




(h)

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 16

MILLING CUTTERS

6. Angle milling cutters, used on horizontal milling machines, for the production of longitudinal grooves (Figure 3.41i) or for edge chamfering.




(i)

● Lecture 3: General-Purpose Machine Tools


Dr. Parviz Kahhal ● 17

MILLING CUTTERS

7. End mills are tools of a shank type, which can be mounted on vertical milling machines (or directly in the spindle nose of horizontal milling machines). End mills may be employed in machining keyways (Figure 3.41j) or vertical surfaces (Figure 3.41k).



(j)




(k)

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 18

MILLING CUTTERS

8. Key-cutters are also of the shank type that can be used on vertical milling machines. They may be used for single-pass milling or multipass milling operations (Figures 3.41l and 3.41m).




● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 19

MILLING CUTTERS

9. Form-milling cutters are mounted on horizontal milling machines. Form cutters may be either concave as shown in Figure 3.41n or convex as in Figure 3.41o.




● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 20

MILLING CUTTERS

10. T-slot cutters are used for milling T-slots and are available in different sizes. The T-slot is machined on a vertical milling machine in two steps:

- Slotting with end mill (Figure 3.41j)
- Cutting with T-slot cutter (Figure 3.41p)




• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 21

MILLING CUTTERS

11. Compound milling cutters are mainly used to produce compound surfaces. These cutters realize high productivity and accuracy (Figure 3.41q).




• Lecture 3: General-Purpose Machine Tools

(q)

Dr. Parviz Kahhal • 22

MILLING CUTTERS

12. Inserted tool milling cutters have a main body that is fabricated from tough and less expensive steel. The teeth are made of alloy tool steel, HSS, carbides, ceramics, or cubic boron nitride (CBN) and mechanically attached to the body using set screws and in some cases are brazed. Cutters of this type are confined usually to large-diameter face milling cutters or horizontal milling cutters (Figure 3.41q).




(q)

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 23

MILLING CUTTERS

13. Gear milling cutters are used for the production of spur and helical gears on vertical or horizontal milling machines (Figures 3.41r and 3.41s). Gear cutters are form-relieved cutters, which are used to mill contoured surfaces. They are sharpened at the tooth face. Hobbing machines and gear shapers are used to cut gears for mass production and high accuracy demands.



(r)

(s)

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 24

GENERAL-PURPOSE MILLING MACHINES

- Milling machines are employed for machining flat surfaces, contoured surfaces, complex and irregular areas, slotting, threading, gear cutting, production of helical flutes, twist drills, and spline shafts to close tolerances.
- Milling machines are classified by application into the following categories:
 - General-purpose milling machines, which are used for piece and small-lot production.
 - Special-purpose milling machines, which are designed for performing one or several distinct milling operations on definite WPs. They are used in mass production.

GENERAL-PURPOSE MILLING MACHINES

- The general-purpose milling machines are extremely versatile and are subdivided into these types:
 1. Knee-type
 2. Vertical bed-type
 3. Planer-type
 4. Rotary-table


GENERAL-PURPOSE MILLING MACHINES

- **Knee-Type Milling Machines.**
- The special feature of these machines is the availability of three Cartesian directions of table motion.
- This group is further subdivided into plain horizontal, universal horizontal, vertical, and ram-head knee-type milling machines. The name "knee" has been adopted because it features a knee that mounts the worktable and travels vertically along the vertical guideway of the machine column.

GENERAL-PURPOSE MILLING MACHINES

- In plain horizontal milling machines, the spindle is horizontal and the table travels in three mutually perpendicular directions. The universal horizontal milling machines (Figure 3.42) are similar in general arrangement to the plain horizontal machines.
- The principal difference is that the table can be swiveled about its vertical axis through $\pm 45^\circ$, which makes it possible to mill helical grooves and helical gears.
- In contrast to horizontal milling machines, vertical-type milling machines have a vertical spindle and no overarm (Figure 3.43).
- The overarm serves to hold the bearing bracket supporting the outer end of the tool arbor in horizontal machines.

GENERAL-PURPOSE MILLING MACHINES



Universal horizontal-spindle milling machine.

● Lecture 3: General-Purpose Machine Tools




FIGURE 3.43 Vertical milling machine.

Dr. Parviz Kahhal ● 29

GENERAL-PURPOSE MILLING MACHINES

- The ram-head milling machines (Figure 3.44) differ from the universal type in that they have an additional spindle that can be swiveled about both the vertical and horizontal axes.
- In ram-head milling machines, the spindle can be set at any angle in relation to the WP being machined.
- In modern machines, a separate drive for the principal movement (cutter), feed movement (WP), rapid traversal of the worktable in all directions, and a single lever control for changing speeds and feeds are provided. Units and components of milling machines are widely unified.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 30

GENERAL-PURPOSE MILLING MACHINES




FIGURE 3.44 Ram-head milling machine.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 31

GENERAL-PURPOSE MILLING MACHINES

- Horizontal knee-type milling machine specifications are as follows:
 - ✓ Dimensions of table working surface
 - ✓ Maximum table travel in the three Cartesian directions
 - ✓ Maximum angle of table swivel
 - ✓ Arbor diameter
 - ✓ Maximum distance between arbor axis and the overarm underside
 - ✓ Number of spindle speeds
 - ✓ Number of feeds in the three directions
 - ✓ Power and speed of main motor
 - ✓ Power and speed of feed motor
 - ✓ Overall dimensions and net weight

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 32


GENERAL-PURPOSE MILLING MACHINES

- Figure 3.42 visualizes the main parts of the horizontal universal milling machine.
- These are Base (1), column (7), knee (13), saddle (12), table swivel plate with graduation (11), worktable (9), overarm (5), holding bearing bracket (8), main motor (3), spindle (6), speed gearbox (4), feed gearbox (2), feed control mechanism (14), braces (10) to link the overarm with the knee for high-rigidity requirements in heavy-duty milling machines.

GENERAL-PURPOSE MILLING MACHINES

- **Vertical Bed-Type Milling Machines.**
- These machines are rigid and powerful; hence, they are used for heavy duty machining of large WPs (Figure 3.45).
- The spindle head containing a speed gearbox travels vertically along the guideways of the machine column and has a separate drive motor.
- In some machines, the spindle head can be swiveled.
- The work is fixed on a compound table that travels horizontally in two mutually perpendicular directions.
- The adjustment in the vertical direction is accomplished by the spindle head.

GENERAL-PURPOSE MILLING MACHINES



Vertical-bed general-purpose milling machine.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 35

GENERAL-PURPOSE MILLING MACHINES

- **Planer-Type Milling Machine.**
- They are intended for machining horizontal, vertical, and inclined planes as well as form surfaces by means of face, plain, and form milling cutters. These machines are of single or double housing, with one or several spindles; each has a separate drive.
- Figure 3.46 shows a single-housing machine with two spindle heads traveling vertically and horizontally.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 36

GENERAL-PURPOSE MILLING MACHINES




FIGURE 3.46 Planer-type general-purpose milling machine.
● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 37


GENERAL-PURPOSE MILLING MACHINES

- **Rotary-Table Milling Machines.**
- These are also called continuous milling machines, as the WPs are set up without stopping the operation.
- Rotary-table machines are highly productive; consequently, they are frequently used for both batch and mass production.
- The WPs being machined are clamped in fixtures installed on the rotating table (2) (Figure 3.47).
- The machines may be equipped with one or two spindle heads (1).
- When several surfaces are to be machined, the WPs are indexed in the fixtures after each complete revolution of the table.
- The machining cycle provides as many table revolutions as the number of surfaces to be machined.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 38

GENERAL-PURPOSE MILLING MACHINES



Rotary-table milling machine.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 39

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES

- **Cutter Mounting.**
- The nose of milling machine spindles has been standardized. It is provided with a locating flange $\phi H7/h6$ and a steep taper socket of 7:24 (1:3.4286) corresponding to an angle of $16^\circ 35.6'$ (Figure 3.48) to ensure better location of arbor and end mill shanks.
- Rotation is transmitted to the cutter through the driving key secured to the end face of the spindle.
- Large face milling cutters are
- mounted directly on the spindle flange and are secured to the flange by four screws, whereas rotation is transmitted to the cutter through the driving keys on the spindle (Figure 3.48).

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 40

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES




FIGURE 3.48 Typical nose of milling machine spindle.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 41

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES

- Plain and side milling cutters are mounted on an arbor whose taper shank is drawn up tight into the taper socket of the spindle (2) with a draw-in bolt 1 (Figure 3.49).
- Milling arbors are long or short (stub arbors).
- The outer end of the long arbor (3) is supported by an overarm support (5) in horizontal milling machines, and the cutter (4) is mounted at the required position on the arbor by a key (or without key in case of slitting saws) and is clamped between collars or spacers (6) with a large nut.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 42

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES




FIGURE 3.49 Milling machine arbor.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 43

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES

- The system shown in Figure 3.50 is used in the duplex bed milling machines. On the stub arbors, the shell end mill or the face milling cutters are driven either by a feather key, as shown in Figure 3.50a, or an end key (Figure 3.50b).
- End mills, T-slot cutters, and other milling cutters of tapered shanks are secured with a draw-in bolt directly in the taper socket of the spindle by means of adaptors (Figure 3.51a). Straight shank cutters are held in chucks (Figure 3.51b).

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 44

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES




FIGURE 3.50 Mounting of end mills and face milling cutters on duplex-bed milling machine.
● Lecture 3: General-Purpose Machine Tools Dr. Parviz Kahhal ● 45

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES




FIGURE 3.51 Mounting of (a) tapered and (b) straight-shank milling cutters.

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES

- **Workpiece Fixturing.**
- Large WPs and blanks that are too large for a vise are clamped directly on the worktable using standard fastening elements such as strap clamps, support blocks, and T-bolts (Figure 3.52).
- Small WPs and blanks are clamped most frequently in general-purpose plain, swivel, or universal milling vises fastened to the worktable (Figure 3.53).
- Shaped jaws are sometimes used instead of the flat type to clamp parts of irregular shapes.
- For more accurate and productive work, expensive milling fixtures are frequently used.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 47

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES





FIGURE 3.53 Vises for clamping of small WPs on milling machines: (a) plain vise, (b) swivel vise, and (c) universal vise.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 48

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES



Clamping of large WPs directly on the worktable.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 49

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES

- Figure 3.54 shows a simple milling fixture for a bearing bracket. A full-form and a flatted locator, firmly fitted into the base plate, are used to locate the WP from two previously machined holes.
- The clamping is effected by two solid clamps.
- To achieve correct alignment and, hence, increased accuracy, a tool-setting block is used to locate the cutter with respect to the WP.
- Figure 3.54 illustrates how the height of the cutter is setup using setting blocks and 0.7 mm feeler.
- The main body of the fixture is frequently made of CI because of its ability to absorb vibrations initiated by the milling operation.
- However, welded and other steel constructions are also used for various specialized purposes.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 50

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES




FIGURE 3.54 Simple milling fixture for a bearing bracket. (From Mott, L. C., *Engineering Drawing and Construction*, Oxford University Press, Oxford, 1976. With permission.)

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 51

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES

- Figure 3.55 illustrates a vise used as a fixture for milling six cylindrical WPs in one clamp.
- The setting block is designed for a feeler gage of 0.025 mm, the thickness of which should be stamped on the setting block in some suitably prominent position.
- In this type of fixture, it is essential that
- when the components are unloaded, all the swarf must be removed; otherwise, the component subsequently loaded into the fixture will not seat correctly.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 52

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES




FIGURE 3.55 Special fixture for milling six cylindrical WPs. (From Mott, L. C., *Engineering Drawing and Construction*, Oxford University Press, Oxford, 1976. With permission.)

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 53

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES

- Figure 3.56 shows a WP and fixture of more specialized nature designed by the U.S. Naval Gun Factory. Two rectangular components are to be milled together.
- They are located and clamped between two mating surfaces.
- The holding plate is positioned by two spring-loaded dowels and a central fixing stud.
- A setting block is doweled and screwed to the fixture.
- It is designed for use with a feeler gage of 0.08 mm thickness.
- The disadvantage of this setup is that the arbor is unsupported at its free end and, therefore, only light cuts are taken.
- Duplex milling machines enable WPs to be machined from both sides at once to ensure high accuracy and enhance productivity.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 54

HOLDING CUTTERS AND WORKPIECES ON MILLING MACHINES




FIGURE 3.56 A special milling fixture for mounting two rectangular components. (From Mott, L. C., *Engineering Drawing and Construction*, Oxford University Press, Oxford, 1976. With permission.)

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 55

DIVIDING HEADS

- Dividing heads are attachments that extend the capabilities of the milling machines.
- They are mainly employed on knee-type milling machines to enhance their capabilities toward milling straight and helical flutes, slots, grooves, and gashes whose features are equally spaced about the circumference of a blank (and less frequently unequally spaced).
- Such jobs include milling of spur and helical gears, spline shafts, twist drills, reamers, milling cutters, and others. Therefore, dividing heads are capable of indexing the WP through predetermined angles.
- In addition to the indexing operation, the dividing head continuously rotates the WP, which is set at the required helix angle during milling of helical slots and helical gears.

● Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal ● 56


DIVIDING HEADS

- There are several versions of dividing heads:
 - Plain dividing heads (Figure 3.57) are mainly used for indexing milling fixtures.
 - Universal dividing heads.
 - Optical dividing heads are commonly used for precise indexing, and also for checking the accuracy of marking graduation lines on dial scales. Their main drawback is that they cannot be used in milling of helical gears.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 57

DIVIDING HEADS



Plain milling dividing head.

• Lecture 3: General-Purpose Machine Tools


Dr. Parviz Kahhal • 58

SHAPERS, PLANERS, AND SLOTTERS AND THEIR OPERATIONS

- **Shaping, Planing, And Slotting Processes.**
- These processes are used for machining horizontal, vertical, and inclined flat and contoured surfaces, slots, grooves, and other recesses by means of special single-point tools.
- The difference between these three processes is that in planing, the work is reciprocated and the tool is fed across the work, while in shaping and slotting, the tool is reciprocating and the work is fed across the cutting tool.
- Moreover, the tool travel is horizontal in shaping and planing and vertical in case of slotting (Figure 3.63).

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 59



SHAPERS, PLANERS, AND SLOTTERS AND THEIR OPERATIONS

- The essence of these processes is the same as of turning, where metals are removed by single point tools similar in shape to lathe tools.
- A similarity also exists in chip formation. However, these operations differ from turning in that the cutting action is intermittent, and chips are removed only during the forward movement of the tool or the work. Moreover, the conditions under which shaping, planing, and slotting tools are less favorable than in turning, even though the tools have the opportunity to cool during the return stroke, when no cutting takes place.

SHAPERS, PLANERS, AND SLOTTERS AND THEIR OPERATIONS

- That is because these tools operate under severe impact conditions.
- For these conditions, the related machine and tools are designed to be more rigid and strongly dimensioned, and the cutting speed in most cases does not exceed 60 m/min.
- Consequently, tools used in these processes should not be shock-sensitive, such as ceramics and CBN.
- It is sufficient to use low-cost and easily sharpened tools such as HSS and carbides.

SHAPERS, PLANERS, AND SLOTTERS AND THEIR OPERATIONS

- The limited cutting speed and the time lost during the reverse stroke are the main reasons behind the low productivity of shaping, planing, and slotting compared to turning.
- However, in planing, not only the productivity but also the accuracy are enhanced due to the possibility of using multiple tooling in one setting.
- Figure 3.64 illustrates the kinematics and machining parameters in shaping, planing, and slotting.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 63

SHAPERS, PLANERS, AND SLOTTERS AND THEIR OPERATIONS




FIGURE 3.64 Kinematics and machining parameters in (a) shaping and planing and (b) slotting.

• Lecture 3: General-Purpose Machine Tools

Dr. Parviz Kahhal • 64

SHAPERS, PLANERS, AND SLOTTERS AND THEIR OPERATIONS

- The basic machining parameters are the average speed during the cutting stroke v_{cm} , the feed f , the depth of cut t , and the uncut cross-section area A_c .
- The feed is the intermittent relative movement of the tool (in planing) or the WP (in shaping and slotting), in a direction perpendicular to the cutting motion and expressed in millimeters per stroke.
- The feed movement is always actuated at the end of the return stroke when the tool is not engaged with the work.
- The depth of cut is the layer removed from the WP in millimeters in a single pass and is measured perpendicular to the machined surface.

SHAPERS, PLANERS, AND SLOTTERS AND THEIR OPERATIONS

- The uncut chip cross-section in square millimeters is given by the following equation for shaping and planing:

$$A_c = b \cdot h = t \cdot f \text{ mm}^2$$

where

b = chip contact length (mm)

= $t/\sin x$

h = chip thickness (mm)

= $f \sin x$

x = setting angle (frequently $x = 75^\circ$)

and the following equation for slotting

$$A_c = b \cdot f \text{ mm}^2$$

where b is the slot width (mm).

SHAPERS, PLANERS, AND SLOTTERS AND THEIR OPERATIONS

- v_{cm} in meters per minute can be calculated depending on the type of machine mechanism.
- It should not exceed the permissible cutting speed which depends upon:
- Machining conditions (depth of cut, feed, tool geometry, and related conditions)
- Tool material used
- Properties of WP material